



report date: 2024-03-29

General information

Make	HONDA
Model	FR-V CTDI SPORT
Colour	Grey
Year of manufacture	2005
Top speed	103 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.204 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-17
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-24
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	24
Total items failed	11

MOT #24	2024-04-04 11:51
MOT test number	322685887577
Result	✓ Passed
Next expiry date	2025-04-24
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))

MOT #23	2023-04-25 15:14
MOT test number	561763264800
Result	✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #22**

2023-04-17 13:20

MOT test number

881176213847

Result

✗ Failed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #21**

2022-04-16 08:27

MOT test number

544548568959

Result

✓ Passed

Advice Nearside Rear Outer sill corroded**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #20**

2021-03-25 12:42

MOT test number

246273113023

Result

✓ Passed

Advice Headlamp has a product on the lens but not seriously reducing light output nearside & offside (4.1.4 (b))**MOT #19**

2021-03-22 13:48

MOT test number

990347715166

Result

✗ Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure outer sidewall (5.2.3 (d) (ii))**Advice** Headlamp has a product on the lens but not seriously reducing light output nearside & offside (4.1.4 (b))

**MOT #18** 2020-04-20 13:13**MOT test number** 333853652314**Result** Passed**MOT #17** 2020-03-24 09:31**MOT test number** 411223380075**Result** Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #16** 2019-03-22 12:15**MOT test number** 955464174258**Result** Passed**MOT #15** 2019-03-21 16:56**MOT test number** 909411666541**Result** Failed**Fail** Tyre tread depth below requirements of 1.6mm both fronts (5.2.3 (e))**MOT #14** 2018-03-13 17:12**MOT test number** 791629241199**Result** Passed**Advice** Nearside Front Tyre worn close to the legal limit inner shoulder (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit inner shoulder (4.1.E.1)**MOT #13** 2017-03-22 14:57**MOT test number** 412315689179**Result** Passed

**MOT #12** 2016-03-29 09:13**MOT test number** 755837968703**Result** ✓ Passed**Advice** Tyre worn close to the legal limit and showing signs deterioration, offside front (4.1.E.1)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #11** 2016-03-24 10:01**MOT test number** 955928464978**Result** ✗ Failed**Advice** Tyre worn close to the legal limit and showing signs deterioration, offside front (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #10** 2015-03-11 10:35**MOT test number** 868970475071**Result** ✓ Passed**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #9** 2015-03-11 10:35**MOT test number** 279220975045**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #8** 2014-03-18 14:15**MOT test number** 525607174081**Result** ✓ Passed

**MOT #7** 2014-03-18 12:07**MOT test number** 166997074469**Result** ✗ Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

MOT #6 2013-03-26 14:50**MOT test number** 128645583455**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Nearside & offside front wiper blades showing sign deterioration.

MOT #5 2012-03-23 10:36**MOT test number** 128243682419**Result** ✓ Passed

Notice N/S/R tyre worn 3mm

MOT #4 2011-03-30 09:36**MOT test number** 629849981086**Result** ✓ Passed**MOT #3** 2010-03-30 20:20**MOT test number** 424399680014**Result** ✓ Passed

Advice Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2009-03-04 17:44
MOT test number	801753269021
Result	✓ Passed
MOT #1	2008-06-04 09:33
MOT test number	362796258136
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
24 April 2025

Tax status	Valid until 1 November
Days left	187
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-09-19
Last registration	2024-04-04
Complete history	See info



Registration #1	2005-09-19	15 mi
Registration #2	2008-06-04	52.353 mi
Registration #3	2009-03-04	57.120 mi
Registration #4	2010-03-30	64.886 mi
Registration #5	2011-03-30	71.279 mi
Registration #6	2012-03-23	78.156 mi
Registration #7	2013-03-26	82.425 mi
Registration #8	2014-03-18	88.257 mi
Registration #9	2014-03-18	88.260 mi
Registration #10	2015-03-11	92.953 mi
Registration #11	2016-03-24	99.358 mi
Registration #12	2016-03-29	99.821 mi
Registration #13	2017-03-22	106.445 mi
Registration #14	2018-03-22	113.069 mi
Registration #15	2019-03-22	119.693 mi
Registration #16	2020-03-22	126.317 mi
Registration #17	2021-03-22	132.941 mi
Registration #18	2022-03-22	139.565 mi
Registration #19	2023-03-22	146.189 mi
Registration #20	2024-03-22	152.813 mi
Registration #21	2025-03-22	159.437 mi
Registration #22	2026-03-22	166.061 mi
Registration #23	2027-03-22	172.685 mi
Registration #24	2028-03-22	179.309 mi
Registration #25	2029-03-22	185.933 mi



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1584 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	N22A11500888