





report date: 2024-03-29

General information

Make	MAZDA
Model	6 D SE-L
Colour	Red
Year of manufacture	2015
Top speed	131 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.200 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	107 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-08-06
Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-05
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	18
Total items failed	1

MOT #8		2023-09-06 13:22
MOT test	number	196155072392
Result		✓ Passed
Next expi	ry date	2024-09-05
Advice	Offside Front Tyre worn close to legal limit/worn on edge <2mm (5.2.3 (e))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material co	rroded (1.1.11 (c))

MOT #7	2023-09-01 08:	52
MOT test r	number 24143829819	99
Result	× Faile	ed
Advice	Offside Front Tyre worn close to legal limit/worn on edge <2mm (5.2.3 (e))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))	
MAJOR	Brake pipe excessively corroded @ osr (1.1.11 (c))	
MAJOR	Brake pipe excessively corroded @ nsr (1.1.11 (c))	

MOT #6	2022-08-31 13:54
MOT test number	111538857160
Result	✓ Passed
Advice Surface rust under body	

CarCheck.co.uk page 3/12



Advice

SM65PHJ

report date: 2024-03-29

MOT #5 2021-09-01 14:45 **MOT** test number 190345223559 Result ✓ Passed 2020-10-19 13:28 **MOT #4 MOT** test number 376225086971 Result ✓ Passed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-10-19 13:27 600359379853 **MOT** test number Result Failed **Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2

MOT test number

940888098510

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



MOT #1 2018-10-20 10:30

MOT test number 155345190537

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Expires: 5 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	5 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



factor scincore

SM65PHJ

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MAZDA had different number plates. door of plates

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-10-30
Last registration	2023-09-06
Complete history	See info



Registration #1	2015-10-30	18 mi
Registration #2	2018-10-20	54.944 mi
Registration #3	2019-10-26	78.614 mi
Registration #4	2020-10-19	95.107 mi
Registration #5	2020-10-19	95.107 mi
Registration #6		77.777 es
Registration #6 Registration #7		11.777 es
-		11.77 m
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1450 mm
Length	4870 mm
Wheel base	2830 mm
Kerb weight	1405 kg
Max. allowed weight	2055 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	SH 30545727

CarCheck.co.uk page 12/12