



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	VECTRA DESIGN CDTI 16V
Colour	Black
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	150 BHP
Max. torque	315 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	186 g/km
CO2 label	J






Internet history

Entry 1

Date	2022-01-14
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-08
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	35
Total items failed	6

MOT #20	2023-06-02 14:43
MOT test number	209816502656
Result	✓ Passed
Next expiry date	2024-06-08
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))

MOT #19	2022-05-28 14:19
MOT test number	367298530317
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #18**

2022-05-28 08:54

**MOT test number**

825214505057

**Result****✗ Failed****MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #17**

2021-06-09 17:29

**MOT test number**

855532131702

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16**

2020-07-10 18:05

**MOT test number**

187289349234

**Result****✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2020-07-08 15:57

**MOT test number**

924202745481

**Result****✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #14**

2019-08-28 12:13

**MOT test number**

946213006386

**Result**

✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13**

2018-07-30 12:26

**MOT test number**

522725164307

**Result**

✓ Passed

- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear exhaust mount is broken

**MOT #12**

2018-07-30 10:39

**MOT test number**

484089372625

**Result**

✗ Failed

- Advice** Rear exhaust mount is broken
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))

**MOT #11** 2017-08-05 14:43**MOT test number** 476394795882**Result** ✓ Passed**Advice** Exhaust corroded**Advice** Front Tyre worn close to the legal limit Both tyres inner edges worn (4.1.E.1)**MOT #10** 2017-08-05 14:43**MOT test number** 618468936274**Result** ✗ Failed**Advice** Front Tyre worn close to the legal limit Both tyres inner edges worn (4.1.E.1)**Pass with rectification** Offside Front coil spring broken (2.4.C.1a)**Advice** Exhaust corroded**MOT #9** 2016-08-30 09:21**MOT test number** 838594131246**Result** ✓ Passed**MOT #8** 2016-08-30 09:21**MOT test number** 846813763194**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #7** 2015-08-22 08:05**MOT test number** 696583125591**Result** ✓ Passed

**MOT #6** 2014-08-27 09:52**MOT test number** 498949334247**Result** ✓ Passed**MOT #5** 2014-08-26 15:42**MOT test number** 305158534279**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2012-09-29 11:18**MOT test number** 139723972290**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-09-09 09:57**MOT test number** 466222351289**Result** ✓ Passed**MOT #2** 2011-09-09 09:25**MOT test number** 257942351275**Result** ✗ Failed**Notice** Uneven tyre wear on rears.**Fail** Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Notice** Metal in offside front tyre.



MOT #1	2011-03-17 10:51
MOT test number	447946871064
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
8 June 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	8 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>FN08VAK</b>
Plate since	2024-03-29
Current registration	 <b>FN08VAK</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-04-16
Last registration	2023-06-02
Complete history	<a href="#">See info</a>



Registration #1	2008-04-16	6 mi
Registration #2	2011-03-17	61.668 mi
Registration #3	2011-09-09	69.769 mi
Registration #4	2011-09-09	69.769 mi
Registration #5	2012-09-29	74.671 mi
Registration #6	2014-08-26	86.784 mi
Registration #7	2014-08-27	86.784 mi
Registration #8	2015-08-22	92.317 mi
Registration #9	2016-08-30	99.160 mi
Registration #10	2016-08-30	99.160 mi
Registration #11	2017-08-05	106.724 mi
Registration #12	2018-06-20	114.388 mi
Registration #13	2019-06-20	122.052 mi
Registration #14	2020-06-20	129.716 mi
Registration #15	2021-06-20	137.380 mi
Registration #16	2022-06-20	145.044 mi
Registration #17	2023-06-20	152.708 mi
Registration #18	2024-06-20	160.372 mi
Registration #19	2025-06-20	168.036 mi
Registration #20	2026-06-20	175.700 mi
Registration #21	2027-06-20	183.364 mi
Registration #22	2028-06-20	191.028 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1504 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	17310665