





report date: 2024-03-29

#### General information

Make	SUZUKI
Model	ALTO SZ2
Colour	White
Year of manufacture	2011
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 сс
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/12



# MOT history

MOT expiry date	2024-05-15
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	16
Total items failed	9

MOT #15		2023-05-16 12:15
MOT test	number	843192761672
Result		<b>✓</b> Passed
Next expi	y date	2024-05-15
Advice Lower arm	Nearside Front Lower Suspension arm pin or bush worn but not resultin (5.3.4 (a) (i))	g in excessive movement -
Advice	Front Headlamp has a product on the lens but not seriously reducing lig	ght output - Both (4.1.4 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice arm (5.3.4	Offside Front Suspension arm pin or bush worn but not resulting in exce (a) (i))	essive movement - Lower
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii	))

CarCheck.co.uk page 2/12



**MOT #14** 2023-05-15 09:49

MOT test number 684405951051

**Result** X Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement - Lower arm (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

Advice Front Headlamp has a product on the lens but not seriously reducing light output - Both (4.1.4 (b))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement - Lower arm (5.3.4 (a) (i))

Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #13 2022-04-06 08:55

MOT test number 336236902020

Result \rightarrow Passed

**Minor** Front Suspension arm ball joint dust cover severely deteriorated both sides ball joint dust cover cracking. (5.3.4 (b) (i))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement front wishbone arms rear bushes. (5.3.4 (a) (i))

**MOT #12** 2021-04-10 11:20

**MOT test number** 133763709056

**Result** ✓ Passed

**MOT #11** 2021-04-10 11:20

MOT test number 955132238488

Result X Failed

**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 3/12



**MOT #10** 2020-03-13 15:56

**MOT test number** 380856060693

MOT #9 2020-03-13 11:27

**MOT test number** 645240785311

Result X Failed

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure distorted (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8 2019-03-18 11:28

MOT test number 150557074914

MOT #7 2018-03-22 15:24

**MOT test number** 999914668580

Result \rightarrow Passed

MOT #6 2018-03-22 15:24

MOT test number 516984323520

Result X Failed

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

CarCheck.co.uk page 4/12



MOT #5	2017-03-30 09:39
MOT test number	342003130024
Result	✓ Passed
MOT #4	2016-03-31 16:32
MOT test number	920011558937
Result	✓ Passed
MOT #3	2015-03-20 10:06
MOT test number	337209275026
Result	✓ Passed
MOT #2	2014-03-08 09:44
MOT test number	475277864062
Result	✓ Passed
MOT #1	2014-03-04 12:59
MOT test number	139553964074
Result	<b>x</b> Failed
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	15 May 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
HARMAN CO. C.	
********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-02
Last registration	2023-05-16
Complete history	See info



Registration #1	2011-03-02	13 mi
Registration #2	2014-03-04	11.680 mi
Registration #3	2014-03-08	11.707 mi
Registration #4	2015-03-20	18.513 mi
Registration #5	2016-03-31	24.631 mi
Registration #6	2017-03-30	29.239 mi
Registration #7	2018-03-22	31.990 mi
Registration #8	2018-03-22	31.990 mi
Registration #9		9.77 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		10.777 mg

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



# Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

## Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	K10BN 1412346

CarCheck.co.uk page 12/12