





report date: 2024-03-28

## General information

Make	FORD
Model	FIESTA ST-3
Colour	Blue
Year of manufacture	2019
Top speed	144 mph
0 - 100 km/h	6.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	147 kW / 200 HP / 197 BHP
Max. torque	290 Nm at 4.000 rpm
Engine capacity	1.496 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	40.4 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 3

Date 2022-02-07

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

#### Entry 2

Date	2021-12-02

Pictures 34

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-12-02	
Pictures	0	
Listing price	<u>View report</u>	

source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

N/I	$\alpha$		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-01-23
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	7
Total items failed	4

MOT #4	2024-01-22 12:38
MOT test number	823798705706
Result	✓ Passed
Next expiry date	2025-01-23

MOT #3	2024-01-22 12:38
MOT test number	352464243438
Result	<b>▼</b> Failed
Pass with rectification affected by an obstruction n	Driver's view of the road through the swept area of the windscreen significantly nirror hangings (3.1 (a) (ii))
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))

MOT #2		2023-01-24 14:12
MOT test	number	588092542258
Result		✓ Passed
Advice Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2021-11-24 16:41 **MOT test number** 323510507525 Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



KP19GNR report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	23 January 2025
Full MOT history	See MOT history

### Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-28

## Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
***************************************	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK SILVE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2019-08-31
Last registration	2024-01-22
Complete history	See info



Registration #1	2019-08-31	19 mi
Registration #2	2021-11-24	28.417 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.117 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	84%
Pedestrian	64%
Safety systems	60%
Overall rating	76%
Video	see crash video



# Dimensions & weight

Width	1941 mm
Height	1469 mm
Length	4068 mm
Wheel base	2493 mm
Kerb weight	1262 kg
Max. allowed weight	1635 kg

# Additional information

Fuel tank capacity	42	
Number of doors	3	
Number of seats	5	
Number of axles CarCheck.co.uk	2	page 11/11

**Engine number** 

JA33964