



report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D4 SE
Colour	Grey
Year of manufacture	2014
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	65.7 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-11-08
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-15
Pictures	41
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-05-19
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	9
Total items failed	5

MOT #9 2023-05-04 09:24

MOT test number 488653024596

Result ✓ Passed

Next expiry date 2024-05-19

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

MOT #8 2022-05-20 11:32

MOT test number 484029179989

Result ✓ Passed

MOT #7 2021-09-08 11:11

MOT test number 870192245493

Result ✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2021-07-16 14:58**MOT test number** 952316714903**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.00mm (5.2.3 (e))**Advice** Under-trays fitted obscuring some underside components" "Engine covers fitted obscuring some components in the engine bay,**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Nearside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))**Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #5** 2020-11-19 08:51**MOT test number** 136770182672**Result** ✓ Passed**MOT #4** 2019-12-05 12:36**MOT test number** 442885058114**Result** ✓ Passed**MOT #3** 2018-12-07 11:36**MOT test number** 784138521515**Result** ✓ Passed**MOT #2** 2018-12-07 11:36**MOT test number** 960456379487**Result** ✗ Failed**Pass with rectification** Fuel system component leaking excessively or a risk of fire filter seal (6.1.3 (b) (ii))**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))



MOT #1	2017-10-13 11:32
MOT test number	129216948853
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
19 May 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	19 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BK64ZVF
Plate since	2024-03-28
Current registration	BK64ZVF
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	12
First mileage registration	2014-10-03
Last registration	2023-05-04
Complete history	See info



Registration #1	2014-10-03	6 mi
Registration #2	2017-10-13	78.494 mi
Registration #3	2018-12-07	85.178 mi
Registration #4	2018-12-07	85.178 mi
Registration #5	2019-12-05	89.175 mi
Registration #6	2020-11-19	91.954 mi
Registration #7	2020-05-20	91.954 mi
Registration #8	2020-05-20	91.954 mi
Registration #9	2020-05-20	91.954 mi
Registration #10	2020-05-20	91.954 mi
Registration #11	2020-05-20	91.954 mi
Registration #12	2020-05-20	91.954 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1758 kg
Max. allowed weight	2485 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1066143