



General information

Make	VOLKSWAGEN
Model	TIGUAN R LINE TDI 4MOTION
Colour	Blue
Year of manufacture	2010
Top speed	125 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 2

Date 2021-09-08

Pictures 4

Listing price [View report](#)




source: cargurus.co.uk

Entry 1

Date 2021-06-14

Pictures 22

Listing price [View report](#)



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-17
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	28
Total items failed	0

MOT #12 2023-06-07 13:49

MOT test number 474462268597

Result ✓ Passed

Next expiry date 2024-06-17

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both starting to ware on inner edge (5.2.3 (e))

MOT #11 2022-06-18 11:25

MOT test number 352669780091

Result ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2022-06-14 17:39

MOT test number 594978286815

Result ✗ Failed**MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2021-03-12 09:24**MOT test number** 968792734210**Result** ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8 2020-03-16 17:25**MOT test number** 331797930521**Result** ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice N/s front brake slightly sticking.o/s and n/s rear tyres cracking slightly.

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2019-02-12 09:43**MOT test number** 960638856920**Result** ✓ Passed**MOT #6** 2018-07-05 08:19**MOT test number** 762091156339**Result** ✓ Passed

**MOT #5**

2017-06-17 10:07

MOT test number

719400245017

Result

✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Inner Tyre worn close to the legal limit 2mm (4.1.E.1)

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Inner Tyre worn close to the legal limit 2mm (4.1.E.1)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #4

2016-07-09 08:24

MOT test number

689741446405

Result

✓ Passed

Advice Rear tyres stepping on inner edges

Advice Front tyres wearing on inner edges

Advice Emissions to clean to get a reading

MOT #3

2015-06-20 12:15

MOT test number

998381475192

Result

✓ Passed

Notice Items removed from driver's view prior to test

MOT #2

2014-04-30 10:51

MOT test number

549630424157

Result

✓ Passed

Notice Both rear tyres cracking in tread, neareside cut in tread in poor condition



MOT #1	2013-04-24 12:13
MOT test number	806604313173
Result	✓ Passed
Notice	Nearside rear tyre cut in tread
Notice	Both front tyres worn on edges and splitting on inner sidewalls in poor condition
Notice	Nail in offside front tyre



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
17 June 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	17 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 PE10UTR
Plate since	2024-03-28
Current registration	 PE10UTR
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-05-06
Last registration	2023-06-07
Complete history	See info



Registration #1	2010-05-06	23 mi
Registration #2	2013-04-24	21.663 mi
Registration #3	2014-04-30	29.076 mi
Registration #4	2015-06-20	36.834 mi
Registration #5	2016-07-09	43.786 mi
Registration #6	2017-06-17	50.409 mi
Registration #7	2018-07-05	57.704 mi
Registration #8	2019-02-12	58.973 mi
Registration #9	2020-05-01	59.000 mi
Registration #10	2020-05-01	59.000 mi
Registration #11	2020-05-01	59.000 mi
Registration #12	2020-05-01	59.000 mi
Registration #13	2020-05-01	59.000 mi
Registration #14	2020-05-01	59.000 mi
Registration #15	2020-05-01	59.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	79%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4427 mm
Wheel base	2604 mm
Kerb weight	1609 kg
Max. allowed weight	2240 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

CBB 328529