





report date: 2024-03-29

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 ENTERPRISE P/V HDI
Colour	White
Year of manufacture	2016
Top speed	90 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I



CarCheck.co.uk page 1/12



Internet history


Entry 1

Date 2021-07-12

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-21
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	19
Total items failed	0

MOT #8	2023-11-22 11:12
MOT test number	821558964974
Result	✓ Passed
Next expiry date	2024-11-21

MOT #7	2023-11	1-21 09:51
MOT test	number 2490	78558307
Result		X Failed
MAJOR	Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))	
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	

MOT #6		2022-08-08 09:29
MOT test	number	590845383065
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		

CarCheck.co.uk page 3/12



MOT #5 2022-07-29 12:44

MOT test number 228624283500

Result X Failed

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

DANGEROUS Nearside Front Outer Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #4 2021-07-21 13:15

MOT test number 298404755978

Result \(\sqrt{Passed} \)

Minor Drive shaft joint constant velocity boot severely deteriorated both front outers (6.1.7 (g) (i))

MOT #3 2021-07-21 11:19

MOT test number 166497668571

Result X Failed

MAJOR Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Drive shaft joint constant velocity boot severely deteriorated both front outers (6.1.7 (g) (i))

MAJOR Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MAJOR Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Central Rear Exhaust mounting defective (6.1.2 (a))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Front Outer Drive shaft joint constant velocity boot severely deteriorated both (6.1.7 (g) (i))

 MOT #1
 2019-04-23 17:06

 MOT test number
 322146104258

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	21 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-05-16
Last registration	2023-11-22
Complete history	See info



Registration #1	2016-05-16	8 mi
Registration #2	2019-04-23	93.141 mi
Registration #3	2020-07-09	114.848 mi
Registration #4		11.777 es
Registration #5	2021-07-21	127.708 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 11/12



Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBDF0089439

CarCheck.co.uk page 12/12