



report date: 2024-03-28

General information

Make	CITROEN
Model	C2 VT
Colour	Red
Year of manufacture	2009
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.300 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-11-17
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-12-02
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	17
Total items failed	20

MOT #20	2022-11-11 11:09
MOT test number	415778291495
Result	✓ Passed
Next expiry date	2023-12-02
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #19	2022-11-05 10:31
MOT test number	563178368427
Result	✗ Failed
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18	2021-12-03 16:14
MOT test number	993045584971
Result	✓ Passed

**MOT #17**

2021-12-03 11:07

MOT test number

902620483439

Result

✗ Failed

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #16

2021-04-20 14:08

MOT test number

969176744456

Result

✓ Passed

Advice Nearside Rear tyre slight cracks on outer wall

MOT #15

2020-05-04 14:30

MOT test number

940116449392

Result

✓ Passed

MOT #14

2020-05-04 13:08

MOT test number

323611662963

Result

✗ Failed

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Headlamp aim too low (4.1.2 (a))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Fail Nearside Headlamp aim too low (4.1.2 (a))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #13** 2019-05-07 15:30**MOT test number** 560099807886**Result** ✓ Passed**MOT #12** 2019-05-07 12:31**MOT test number** 574442473969**Result** ✗ Failed**Fail** Offside Windscreen washer not working (3.5 (a))**Fail** Nearside Windscreen washer not working (3.5 (a))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))**MOT #11** 2018-04-30 13:07**MOT test number** 340376562615**Result** ✓ Passed**MOT #10** 2017-05-08 11:52**MOT test number** 858860074400**Result** ✓ Passed**MOT #9** 2017-05-08 09:58**MOT test number** 157429627920**Result** ✗ Failed**Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)

**MOT #8** 2016-03-11 15:07**MOT test number** 348682329180**Result** ✓ Passed**Advice** Nearside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear tyre slightly perished**Advice** Nearside Front tyre slight wear outer edge**Advice** Offside Rear tyre slightly perished**MOT #7** 2016-03-11 11:02**MOT test number** 219579310517**Result** ✗ Failed**Advice** Nearside Front tyre slight wear outer edge**Advice** Offside Rear tyre slightly perished**Advice** Nearside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear tyre slightly perished**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both nearside and offside (3.5.1i)**MOT #6** 2015-03-20 17:26**MOT test number** 915659175013**Result** ✓ Passed

**MOT #5** 2015-03-20 17:26**MOT test number** 246849575039**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #4** 2014-09-29 11:18**MOT test number** 795992874266**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2013-09-19 12:43**MOT test number** 639912563266**Result** ✓ Passed**MOT #2** 2013-09-06 10:28**MOT test number** 627599043292**Result** ✗ Failed**Fail** Offside Front Seat belt stitching badly frayed (5.2.2b)**Fail** Nearside Front Headlamp aim too low (1.8)**MOT #1** 2012-09-11 11:04**MOT test number** 889195052270**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
31 July 2023

X

MOT

Expired:
2 December 2023

Tax status	Expired at 31 July 2023
Days left	273 days too late
MOT expiry date	2 December 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-16
Last registration	2022-11-11
Complete history	See info



Registration #1	2009-09-16	27 mi
Registration #2	2012-09-11	11.855 mi
Registration #3	2013-09-06	16.044 mi
Registration #4	2013-09-19	16.182 mi
Registration #5	2014-09-29	20.207 mi
Registration #6	2015-03-20	23.157 mi
Registration #7	2016-03-11	32.665 mi
Registration #8	2016-03-11	32.667 mi
Registration #9	2017-05-08	36.245 mi
Registration #10	2017-05-08	36.245 mi
Registration #11	2018-04-30	37.991 mi
Registration #12	2019-05-20	38.277 mi
Registration #13	2019-05-20	38.277 mi
Registration #14	2019-05-20	38.277 mi
Registration #15	2019-05-20	38.277 mi
Registration #16	2019-05-20	38.277 mi
Registration #17	2019-05-20	38.277 mi
Registration #18	2019-05-20	38.277 mi
Registration #19	2019-05-20	38.277 mi
Registration #20	2019-05-20	38.277 mi
Registration #21	2019-05-20	38.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	956 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7W5123324