





report date: 2024-03-29

General information

Make	VOLVO
Model	S60 T4 SE NAV
Colour	Blue
Year of manufacture	2018
Top speed	143 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	187 BHP
Max. torque	300 Nm at 1.300 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	131 g/km
CO2 label	Е



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-02-06

Pictures 6

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-03-15
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #5		2024-03-16 15:04
MOT test	number	722814454700
Result		✓ Passed
Next exp	ry date	2025-03-15
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamp	s or light sources (4.7.1
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Vehicles internal headlight adjuster altered to recheck lights	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #4		2024-03-15 14:48
MOT test	number	621535466208
Result		X Failed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Vehicles internal headlight adjuster altered to recheck lights	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail (5.2.3 (d)	Offside Rear Tyre has a cut in excess of the requirements deep enough to reaction)	ch the ply or cords
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps o	r light sources (4.7.1

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2023-03-10 13:35 941346486528 **MOT** test number ✓ Passed Result **Advice** Under trays fitted **Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e)) Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald on edges & tread damaged (5.2.3 (e)) **Advice** Offside Front Tyre slightly damaged edges of tread (5.2.3 (d) (ii))

MOT #2

MOT test number

829807955234

Result

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1

MOT test number

411894971370

Result

Advice Engine cover fitted

Advice Under trays fitted

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

റ	wr	۵r	hi	ict	or۷

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	OK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-04-30
Last registration	2024-03-16
Complete history	See info



Registration #1	2018-04-30	23 mi
Registration #2		71.777 es
Registration #3	2021-03-12	14.187 mi
Registration #4	2022-03-11	24.892 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11,177 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1899 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1512 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	67 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page 1	1/11

Number of axles2Engine number2579161