






report date: 2024-03-29

General information

Make	RENAULT
Model	KANGOO SL 16P 60
Colour	Grey
Year of manufacture	2003
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	105 Nm at 3.500 rpm
Engine capacity	1.149 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 2

Date 2022-03-21

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-09-03

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2024-03-21
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	38
Total items failed	10

MOT #27	2023-03-09 13:46
MOT test number	807914310027
Result	✓ Passed
Next expiry date 2024-03	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #26		2023-03-09 11:34
MOT test	number	658561285860
Result		🗙 Failed
MAJOR	Windscreen washer not working (3.5 (a))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		ii))
MAJOR	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

2022-03-22 13:23
302318497603
✓ Passed
2021-08-11 11:05
779795006783
✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #23 2021-07-30 15:56

MOT test number 425908710860

Result X Failed

MAJOR Offside Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))

MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #22 2020-11-24 16:21

MOT test number 490810773069

Advice Brake pipe corroded, covered in grease or other material BOTH FRONT TO REAR (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #21 2020-11-24 09:47

MOT test number 665180582454

Result × Failed

MAJOR Horn not working (7.7 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MAJOR Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

Pass with rectification Windscreen washer not working (3.5 (a))

MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Brake pipe corroded, covered in grease or other material BOTH FRONT TO REAR (1.1.11 (c))

MOT #20 2019-11-27 11:15

MOT test number 541208361208

Result \rightarrow Passed

Advice Front EXHAUST CLAMP CORRODED AWAY BUT NOT LEAKING.

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #19

MOT test number

781656075544

Result

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Brake pipe corroded, covered in grease or other material FRONT TO REAR (1.1.11 (c))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18 2018-12-04 09:17

MOT test number 822101005933

Result × Failed

Advice Brake pipe corroded, covered in grease or other material FRONT TO REAR (1.1.11 (c))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MAJOR Service brake efficiency below requirements (1.2.2 (a) (i))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #17 2017-12-05 18:25

MOT test number 559950677616

Result

Passed

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT test number

Result

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Fail Horn not working (1.6.2a)

Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)

MOT #15

MOT test number

403973208143

Result

Advice Offside Outer Track rod end ball joint has slight play (2.2.B.1f)

MOT test number

Result

Advice Offside Outer Track rod end ball joint has slight play (2.2.B.1f)

Pass with rectification Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #13

MOT test number

Result

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #12 2015-11-23 09:24 **MOT test number** 644501619280 Result **★** Failed Fail Offside Rear Rear wheel bearing rough when rotated (2.6.1) Offside Front Brake pipe slightly corroded (3.6.B.2c) Advice Advice Offside Front front brake fluctuating, but not excessively (3.7.B.3) Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2) Offside Front Valve stem seriously damaged (4.1.D.1e) Fail Fail Nearside Front coil spring broken (2.4.C.1a)

MOT #11		2014-11-24 10:08
MOT test number		905078524361
Result		✓ Passed
MOT #10		2014-11-24 10:08
MOT test number		485438724360
Result		× Failed
Pass with rectification	Centre Stop lamp not working (1.2.1b)	

Pass with rectification	Centre Stop lamp not working (1.2.1b)	
MOT #9		2013-12-09 08:57
MOT test number		668023243323
Result		✓ Passed
MOT #8		2012-11-26 14:55
MOT test number		475341732435
Result		✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

MOT #7	2011-12-12 15:47
MOT test number	678366741309
Result	✓ Passed
MOT #6	2010-12-13 07:41
MOT test number	391017140354
Result	✓ Passed
MOT #5	2009-12-08 08:13
MOT test number	963562949320
Result	✓ Passed
MOT #4	2008-11-24 07:43
MOT test number	911609128368
Result	✓ Passed
MOT #3	2008-11-22 07:38
MOT test number	772137028313
Result	× Failed
Fail Offside Registration plate lamp not working (1.1.5c)	
Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)	

MOT #2		2007-12-04 07:58
MOT test	number	704948737373
Result		✓ Passed
Advice	Nearside Front brake disc slightly scored (3.5.1h)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front brake disc slightly scored (3.5.1h)	

CarCheck.co.uk page 8/14



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 9/14



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	

2000000	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2003-12-22
Last registration	2023-03-09
Complete history	See info



Registration #1	2003-12-22	27 mi
Registration #2	2006-12-07	28.831 mi
Registration #3	2007-12-04	44.706 mi
Registration #4	2008-11-22	61.692 mi
Registration #5	2008-11-24	61.694 mi
Registration #6	2009-12-08	77.494 mi
Registration #7	2010-12-13	84.969 mi
Registration #8	2011-12-12	88.844 mi
Registration #9	2012-11-26	95.940 mi
Registration #10	2013-12-09	103.218 mi
Registration #11	2014-11-24	107.499 mi
Registration #12	2015-11-23	111.679 mi
Registration #13	2015-11-24	111.681 mi
Registration #14	2016-12-01	114.526 mi
Registration #15	2016-12-01	114.526 mi
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		71.777 es
Registration #21		11.777 es
Registration #22		71.777 es
Registration #23		11.777 esi
Registration #24		71.777 es
Registration #25		11.777 es
Registration #26		11.777 es
CarCheck.co.uk		page 13/14

Registration #27	1.77 40
Registration #28	71,777 66
Registration #29	11.777 es

More info >



AX53GPY report date: 2024-03-29

Car features

50225	Air conditionin
60295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2031 mm
Height	1800 mm
Length	4035 mm
Kerb weight	990 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	F370382

CarCheck.co.uk page 14/14