



report date: 2024-03-28

General information

Make	FIAT
Model	PANDA POP DUALOGIC
Colour	Red
Year of manufacture	2011
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	113 g/km
CO2 label	C





## Internet history

### Entry 6

Date 2021-11-08

Pictures 8

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 5

Date 2021-10-12

Pictures 8

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 4

Date 2021-08-04

Pictures 8

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 3

Date 2021-07-20

CarCheck.co.uk

Pictures

8

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

## Entry 2

Date

2021-07-06

Pictures

8

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

## Entry 1

Date

2021-06-19

Pictures

8

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-30
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	40
Total items failed	3

MOT #13	2023-12-14 17:16
MOT test number	504642512151
Result	✓ Passed
Next expiry date	2024-12-30
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12**

2023-12-14 14:23

**MOT test number**

470445525923

**Result****✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm - worn on inner edge (5.2.3 (e))**MAJOR** Emissions unable to be completed (8.2.1.2 (d))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MAJOR** Offside Rear Shock absorbers has an excessively worn bush upper bush (5.3.2 (c))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Exhaust has a major leak of exhaust gases front flexi pipe (6.1.2 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MAJOR** Nearside Rear Shock absorbers has an excessively worn bush upper bush (5.3.2 (c))**MOT #11**

2022-12-20 16:30

**MOT test number**

856665720108

**Result****✓ Passed****Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #10**

2021-12-14 11:35

**MOT test number**

939581798630

**Result****✓ Passed**

**MOT #9** 2020-12-10 16:34**MOT test number** 598062728201**Result** ✓ Passed**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #8** 2019-12-03 14:57**MOT test number** 511137916341**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-12-10 16:04**MOT test number** 816158615423**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2017-12-04 16:18**MOT test number** 975258901680**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Tyre worn close to the legal limit all 4 (4.1.E.1)

**MOT #5** 2016-12-07 13:26**MOT test number** 996347684084**Result** ✓ Passed**MOT #4** 2016-12-07 11:27**MOT test number** 337939849193**Result** ✗ Failed

- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

**MOT #3** 2015-12-09 08:17**MOT test number** 733014428198**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear exhaust box outer casing is loose

**MOT #2** 2015-12-08 15:48**MOT test number** 372697147835**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear exhaust box outer casing is loose
- Fail** Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)
- Fail** Rear Exhaust system not adequately supported exhaust clamp is missing (7.1.1)

**MOT #1** 2014-12-29 12:17**MOT test number** 257513264320**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
30 December 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	30 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation


<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-12-30
Last registration	2023-12-14
Complete history	<a href="#">See info</a>



Registration #1	2011-12-30	21 mi
Registration #2	2014-12-29	15.125 mi
Registration #3	2015-12-08	21.073 mi
Registration #4	2015-12-09	21.073 mi
Registration #5	2016-12-07	26.640 mi
Registration #6	2016-12-07	26.640 mi
Registration #7	2017-12-04	31.667 mi
Registration #8	2018-12-10	39.323 mi
Registration #9	2019-12-03	47.667 mi
Registration #10	2020-12-10	50.690 mi
Registration #11	2020-12-10	50.690 mi
Registration #12	2020-12-10	50.690 mi
Registration #13	2020-12-10	50.690 mi
Registration #14	2020-12-10	50.690 mi
Registration #15	2020-12-10	50.690 mi
Registration #16	2020-12-10	50.690 mi
Registration #17	2020-12-10	50.690 mi
Registration #18	2020-12-10	50.690 mi
Registration #19	2020-12-10	50.690 mi
Registration #20	2020-12-10	50.690 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats 4

<b>Number of axles</b>	2
<b>Engine number</b>	6491843