



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 LX
Colour	Blue
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	111 Nm at 2.600 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-12
Pictures	39
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #25**

2022-04-01 08:40

MOT test number

502248497049

Result**✗ Failed****MAJOR** Brake load sensing valve linkage defective and function impaired (1.1.17 (a))**DANGEROUS** Nearside Rear Shock absorbers likely to become detached (5.3.2 (a) (ii))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Oil leak, but not excessive needs investigation (8.4.1 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Emissions not tested oil level too high (8.2.1.2 (d))**MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Front tyres wearing heavily inner edge**MAJOR** Nearside Rear Position lamp likely to become detached (4.2.1 (c) (ii))**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #24**

2021-03-25 15:32

MOT test number

165865381818

Result**✓ Passed**



MOT #23

2020-03-17 15:29

MOT test number

307395919466

Result

✓ Passed

- Advice
- Nail in offside front tyre
- Advice
- Nearside front tyre slight wear on outer edge
- Advice
- Rear wiper blade perished
- Advice
- Rear petrol tank support strap corroded
- Advice
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice
- Front inner brake pads worn?
- Advice
- Offside front tyre slight wear on inner edge
- Advice
- Rear Brake load sensing valve stiff (1.1.17 (c) (ii))
- Advice
- Drivers door stay worn

**MOT #22**

2020-03-17 15:29

MOT test number

362684665259

Result**✗ Failed****Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nail in offside front tyre**Advice** Rear Brake load sensing valve stiff (1.1.17 (c) (ii))**Advice** Nearside front tyre slight wear on outer edge**Advice** Rear wiper blade perished**Advice** Rear petrol tank support strap corroded**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front inner brake pads worn?**Advice** Offside front tyre slight wear on inner edge**Advice** Drivers door stay worn**MOT #21**

2019-03-05 17:08

MOT test number

354483033425

Result**✓ Passed****Advice** Unable to see front brake pads**Advice** Offside Rear Position lamp slightly affected by the operation of another lamp indicator (4.2.3 (c))**Advice** Rear brake compensator linkage, stiff in operation?**Advice** Offside front door strap inoperative

**MOT #20**

2019-03-04 16:58

MOT test number

575733378734

Result**✗ Failed**

- Advice** Unable to see front brake pads
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Offside front door strap inoperative
- MAJOR** Rear Registration plate inscription illegible delaminated across letters (0.1 (b))
- Advice** Nearside front door strap loose
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear brake compensator linkage, stiff in operation?
- Advice** Offside Rear Position lamp slightly affected by the operation of another lamp indicator (4.2.3 (c))

MOT #19

2018-03-26 16:23

MOT test number

839311225901

Result**✓ Passed**

- Advice** Light switch stalk worn
- Advice** Unable to see front brakes

MOT #18

2018-03-26 15:04

MOT test number

798229742521

Result**✗ Failed**

- Fail** Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp with indicator and brake light (1.1.A.3f)
- Advice** Light switch stalk worn
- Advice** Unable to see front brakes
- Advice** Nearside rear bumper loose / damaged
- Fail** Nearside Rear Tyre fouling a part of the vehicle inner wheel arch trim (4.1.D.2)

**MOT #17**

2017-03-27 15:12

MOT test number

882336660691

Result

✓ Passed

- Advice** Light switch loose
- Advice** Nearside Front Tyre worn close to the legal limit worn outer edge (4.1.E.1)
- Advice** Advice tracking check
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #16

2017-03-14 16:25

MOT test number

911792339943

Result

✗ Failed

- Fail** Offside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Advice tracking check
- Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit worn outer edge (4.1.E.1)
- Advice** Light switch loose

MOT #15

2016-03-15 16:41

MOT test number

221067509208

Result

✓ Passed

- Advice** Offside Rear tyre has nail

**MOT #14**

2016-03-08 16:11

MOT test number

789529804954

Result**✗ Failed****Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Rear tyre has nail**Fail** Offside Rear Brake load sensing valve seized (3.6.E.3)**Fail** Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #13**

2015-03-13 16:12

MOT test number

967622775029

Result**✓ Passed****Advice** Centre Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #12**

2015-03-13 16:12

MOT test number

308662975071

Result**✗ Failed****Advice** Centre Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11**

2014-03-29 12:39

MOT test number

185708284403

Result

✓ Passed

Notice Child seat fitted to n/s/rear not allowing a full inspection of rear seat belts also seats have covers on not allowing access to centre rear seat belt

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #10

2014-03-28 11:10

MOT test number

717637484016

Result

✗ Failed

Fail Brake load sensing valve linkage seized (3.6.E.3)

Fail Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Braking system leaking (3.6.A.1)

Fail Nearside rear brake recording little or no effort (3.7.B.5a)

Fail Rear brake application uneven (3.7.B.2)

Notice Child seat fitted to n/s/rear not allowing a full inspection of rear seat belts also seats have covers on not allowing access to centre rear seat belt

Fail Brakes imbalanced across an axle (3.7.B.5b)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #9

2013-03-27 17:39

MOT test number

775226683042

Result

✓ Passed

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2013-03-27 17:39**MOT test number** 157266383021**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**MOT #7** 2012-03-26 11:02**MOT test number** 627126182007**Result** ✓ Passed**Notice** Offside drive shaft gaiter loose on shaft leaking grease**MOT #6** 2011-03-07 15:14**MOT test number** 158536261003**Result** ✓ Passed**MOT #5** 2010-03-11 13:30**MOT test number** 184750770452**Result** ✓ Passed**MOT #4** 2009-03-18 13:55**MOT test number** 214187679001**Result** ✓ Passed**MOT #3** 2008-03-18 15:06**MOT test number** 294788378051**Result** ✓ Passed



MOT #2	2007-03-12 16:21
MOT test number	470241577009
Result	✓ Passed

MOT #1	2006-03-28 14:44
MOT test number	840797486041
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2002-03-29
Last registration	2022-04-01
Complete history	See info



Registration #1	2002-03-29	6 mi
Registration #2	2006-03-28	10.910 mi
Registration #3	2007-03-12	12.213 mi
Registration #4	2008-03-18	13.496 mi
Registration #5	2009-03-18	15.442 mi
Registration #6	2010-03-11	16.511 mi
Registration #7	2011-03-07	17.385 mi
Registration #8	2012-03-26	19.414 mi
Registration #9	2013-03-27	25.630 mi
Registration #10	2014-03-28	31.660 mi
Registration #11	2014-03-29	31.668 mi
Registration #12	2015-03-13	36.419 mi
Registration #13	2016-03-08	43.029 mi
Registration #14	2016-03-08	43.029 mi
Registration #15	2016-03-08	43.029 mi
Registration #16	2016-03-08	43.029 mi
Registration #17	2016-03-08	43.029 mi
Registration #18	2016-03-08	43.029 mi
Registration #19	2016-03-08	43.029 mi
Registration #20	2016-03-08	43.029 mi
Registration #21	2016-03-08	43.029 mi
Registration #22	2016-03-08	43.029 mi
Registration #23	2016-03-08	43.029 mi
Registration #24	2016-03-08	43.029 mi
Registration #25	2016-03-08	43.029 mi



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	950 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	FSC43814790