



report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO DYNAMIC
Colour	Blue
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	128 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-09
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #17	2021-05-24 09:21
MOT test number	111391264013
Result	✓ Passed
Next expiry date	2022-05-23
Advice	Front washers wired to rear wiper

MOT #16	2021-05-12 17:00
MOT test number	827199970628
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged sidewalls (5.2.3 (d) (ii))
Advice	Front washers wired to rear wiper
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Rear Brakes imbalanced across an axle 37% (1.2.1 (b) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Front Headlamp aim not tested (4.1.2 (b))
Advice	Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt needs clip on inside (6.1.7 (g) (ii))

**MOT #15**

2020-11-13 14:24

MOT test number

333464539372

Result

✓ Passed

Advice Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**MOT #14**

2020-11-13 09:35

MOT test number

854219119046

Result

✗ Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))**MOT #13**

2019-05-17 13:50

MOT test number

561380181555

Result

✓ Passed

Advice Coolant leak

**MOT #12**

2019-05-17 09:18

MOT test number

207468465204

Result**✗ Failed****Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Brake lever has insufficient reserve travel handbrake (1.1.2 (a))**Advice** Coolant leak**MOT #11**

2019-05-15 15:54

MOT test number

323158135607

Result**✗ Failed****Fail** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))**Advice** Coolant leak**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (h) (i))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Fail** Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Rear Inner Position lamp not working (4.2.1 (a))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #10** 2018-04-18 14:34**MOT test number** 973545926341**Result** ✓ Passed**MOT #9** 2017-05-09 13:11**MOT test number** 187292789573**Result** ✓ Passed**Advice** Nearside Front Nail in tyre**MOT #8** 2017-05-08 11:28**MOT test number** 212871643969**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Nail in tyre**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2016-05-16 12:07**MOT test number** 786922496021**Result** ✓ Passed

**MOT #6** 2015-03-10 13:10**MOT test number** 545009365021**Result** ✓ Passed**Notice** Oil leak**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-03-09 14:47**MOT test number** 455168865039**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Oil leak**Fail** Offside Rear Fuel cap/sealing device does not fasten securely by positive means (7.2.4b)**MOT #4** 2014-02-19 13:36**MOT test number** 117920254054**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)



MOT #3	2014-02-15 10:50
MOT test number	335926644040
Result	✗ Failed
Fail	Offside Headlamp aim too low (1.8)
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)
Fail	Nearside Headlamp insecure (1.7.3)
Fail	Nearside Headlamp aim not tested (1.8.A.1c)

MOT #2	2013-03-09 09:23
MOT test number	238598263022
Result	✓ Passed
MOT #1	2012-03-12 15:29
MOT test number	706342372091
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-04-30
Last registration	2021-05-24
Complete history	See info



Registration #1	2009-04-30	8 mi
Registration #2	2012-03-12	21.111 mi
Registration #3	2013-03-09	25.656 mi
Registration #4	2014-02-15	31.623 mi
Registration #5	2014-02-19	31.660 mi
Registration #6	2015-03-09	38.160 mi
Registration #7	2015-03-10	38.160 mi
Registration #8	2016-05-16	41.118 mi
Registration #9	2017-05-08	53.652 mi
Registration #10	2017-05-09	53.655 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi
Registration #14	2019-05-20	55.277 mi
Registration #15	2019-05-20	55.277 mi
Registration #16	2019-05-20	55.277 mi
Registration #17	2019-05-20	55.277 mi
Registration #18	2019-05-20	55.277 mi
Registration #19	2019-05-20	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1307868