



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 SE SPORT
Colour	Blue
Year of manufacture	2007
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	38.2 mpg
Consumption combined	31.4 mpg
CO2 emission	239 g/km
CO2 label	L





## MOT history

MOT expiry date	2023-03-02
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	33
Total items failed	13

MOT #13 2022-03-03 16:36

MOT test number 705109268062

Result ✓ Passed

Next expiry date 2023-03-02

- Advice** Offside Rear tyre crcking
- Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

MOT #12 2022-03-03 09:17

MOT test number 136787321512

Result ✗ Failed

- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Offside Rear tyre crcking
- Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Fail** Fuel system component leaking filter (6.1.3 (b) (i))

**MOT #11** 2021-02-17 15:36**MOT test number** 329415958316**Result** ✓ Passed

- Advice** Nearside Rear Service brake grabbing slightly (1.2.1 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear tyre cracking
- Advice** Offside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

**MOT #10** 2021-02-11 14:11**MOT test number** 397665194633**Result** ✗ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear tyre cracking
- Advice** Nearside Rear Service brake grabbing slightly (1.2.1 (c))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #9** 2019-12-13 14:44**MOT test number** 769943589310**Result** ✓ Passed

- Advice** Both front front suspension arm bushes have slight play but not excessive
- Advice** Nearside Front shocker slight misting of oil

**MOT #8** 2019-12-12 17:10**MOT test number** 147065404461**Result** ✗ Failed**Advice** Both front front suspension arm bushes have slight play but not excessive**Fail** Service brake lagging in operation (1.2.1 (d))**Advice** Nearside Front shocker slight misting of oil**MOT #7** 2018-08-04 08:35**MOT test number** 498071429277**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre Also on 2mm and worn on edges**Advice** N/s/f drop link rubber split but still preventing the ingress of dirt**Advice** O/s/r tyre cracking**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Headlamps deteriorating but not affecting beam image**Advice** N/s/f shock absorber has slight misting of oil**MOT #6** 2017-07-28 13:19**MOT test number** 456439472880**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rears (3.5.1i)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Both head lights deteriorated**Advice** Brake disc worn, pitted or scored, but not seriously weakened both fronts (3.5.1i)

**MOT #5**

2017-07-27 15:03

**MOT test number**

772836695454

**Result****✗ Failed**

- Fail** Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Headlamp aim too high (1.8)
- Fail** Parking brake: efficiency below requirements (3.7.C.1b)
- Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Offside Headlamp aim too high (1.8)

**MOT #4**

2016-08-05 09:22

**MOT test number**

545245189751

**Result****✓ Passed**

- Advice** Front brake discs worn
- Advice** Both front wishbone front bushes deteriorated
- Advice** Both rear brake discs pitted

**MOT #3**

2015-07-06 16:21

**MOT test number**

435847485127

**Result****✓ Passed****MOT #2**

2015-07-06 12:48

**MOT test number**

686887285196

**Result****✗ Failed**

- Fail** Offside Rear position lamp(s) missing (1.1.A.3a)
- Fail** Offside Stop lamp missing (1.2.1a)
- Fail** Offside Direction indicator missing (1.4.A.2b)



MOT #1	2015-01-29 17:43
MOT test number	997009825045
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
30 November 2020

✕  
MOT

Expired:  
2 March 2023

Tax status	Expired at 30 November 2020
Days left	1247 days too late
MOT expiry date	2 March 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>LE56NNT</b>
Plate since	2019-09-29
Current registration	<b>LE56NNT</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-01-18
Last registration	2022-03-03
Complete history	<a href="#">See info</a>



Registration #1	2007-01-18	28 mi
Registration #2	2015-01-29	79.316 mi
Registration #3	2015-07-06	81.685 mi
Registration #4	2015-07-06	81.685 mi
Registration #5	2016-08-05	101.273 mi
Registration #6	2017-07-27	116.297 mi
Registration #7	2017-07-28	116.379 mi
Registration #8	2019-05-29	151.277 mi
Registration #9	2019-05-29	151.277 mi
Registration #10	2019-05-29	151.277 mi
Registration #11	2019-05-29	151.277 mi
Registration #12	2019-05-29	151.277 mi
Registration #13	2019-05-29	151.277 mi
Registration #14	2022-03-03	151.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1743 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2133 kg
Max. allowed weight	2770 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	480157