




General information

Make	VOLKSWAGEN
Model	POLO SE DSG
Colour	Blue
Year of manufacture	2010
Top speed	110 mph
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	85 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	135 g/km
CO2 label	E





MOT history

MOT expiry date	2024-06-05
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	21
Total items failed	6

MOT #15	2023-06-06 15:58
MOT test number	490020294466
Result	✓ Passed
Next expiry date	2024-06-05
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-06-06 17:18
MOT test number	816536190812
Result	✓ Passed

MOT #13	2021-06-04 07:48
MOT test number	315960812322
Result	✓ Passed

**MOT #12**

2020-03-31 10:30

MOT test number

551972186095

Result

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Inner Play in steering rack inner joint(s)
- Advice** Nearside passenger door damaged
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Inner Play in steering rack inner joint(s)

MOT #11

2020-03-31 08:58

MOT test number

247322671916

Result

✗ Failed

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Inner Play in steering rack inner joint(s)
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Inner Play in steering rack inner joint(s)
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside passenger door damaged

MOT #10

2019-04-03 11:06

MOT test number

927776183482

Result

✓ Passed

**MOT #9**

2018-05-01 14:09

MOT test number

921489371095

Result

✓ Passed

Advice Both front tyres worn close to limit on inside edge**Advice** Nearside Front Lower Seat belt anchorage prescribed area is distorted but not considered excessive sill area (5.2.6)**Advice** Slight damage to front number plate**MOT #8**

2018-05-01 14:09

MOT test number

260644349307

Result

✗ Failed

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Both front tyres worn close to limit on inside edge**Advice** Nearside Front Lower Seat belt anchorage prescribed area is distorted but not considered excessive sill area (5.2.6)**Advice** Slight damage to front number plate**MOT #7**

2017-04-13 11:47

MOT test number

742539996624

Result

✓ Passed

MOT #6

2017-04-13 09:04

MOT test number

836904683726

Result

✗ Failed

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2016-04-07 10:11**MOT test number** 331095539945**Result** ✓ Passed**MOT #4** 2015-04-11 10:51**MOT test number** 395621405199**Result** ✓ Passed**MOT #3** 2015-04-11 10:51**MOT test number** 719721205132**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #2** 2014-04-15 10:49**MOT test number** 246105404475**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2013-03-21 15:23**MOT test number** 125480983411**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
5 June 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	5 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	WN10ZDP
Plate since	2019-03-29
Current registration	WN10ZDP
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-04-19
Last registration	2023-06-06
Complete history	See info



Registration #1	2010-04-19	7 mi
Registration #2	2013-03-21	5.212 mi
Registration #3	2014-04-15	15.779 mi
Registration #4	2015-04-11	30.101 mi
Registration #5	2016-04-07	43.503 mi
Registration #6	2017-04-13	51.766 mi
Registration #7	2017-04-13	51.766 mi
Registration #8	2018-05-01	60.654 mi
Registration #9	2019-05-01	69.542 mi
Registration #10	2020-05-01	78.430 mi
Registration #11	2021-05-01	87.318 mi
Registration #12	2022-05-01	96.206 mi
Registration #13	2023-05-01	105.094 mi
Registration #14	2024-05-01	113.982 mi
Registration #15	2025-05-01	122.870 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1104 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CGG 423176