




report date: 2024-03-28

## General information

Make	VAUXHALL
Model	MOVANO F3500 L3H1 C/C CDTI
Colour	White
Year of manufacture	2016
Top speed	80 mph
0 - 60 mph	14.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	123 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	35.0 mpg
Consumption combined	32.0 mpg
CO2 emission	226 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-22
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-18
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	8
Total items failed	5

MOT #6	2023-07-19 15:28
MOT test number	672098598538
Result	✓ Passed
Next expiry date	2024-07-18

MOT #5	2023-07-15 12:51
MOT test number	376297291413
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #4** 2022-09-22 14:59**MOT test number** 651595156984**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2021-09-27 14:38**MOT test number** 475075456647**Result** ✓ Passed**MOT #2** 2020-06-24 11:39**MOT test number** 781834600591**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Seat belt buckle slightly damaged (7.1.2 (d))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1** 2019-04-25 11:05**MOT test number** 787331605329**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
18 July 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	18 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01

More info >





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-04-30
Last registration	2023-07-19
Complete history	<a href="#">See info</a>



Registration #1	2016-04-30	21 mi
Registration #2	2019-04-25	25.019 mi
Registration #3	2020-06-24	34.258 mi
Registration #4	2021-06-29	35.277 mi
Registration #5	2022-06-29	36.297 mi
Registration #6	2023-06-29	37.317 mi
Registration #7	2023-06-29	38.337 mi
Registration #8	2023-06-29	39.357 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2470 mm
Height	2350 mm
Length	6418 mm
Kerb weight	1686 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	M9T -C199830 LWL