





report date: 2024-03-29

## General information

Make	PEUGEOT
Model	5008 HDI SPORT
Colour	Blue
Year of manufacture	2011
Top speed	114 mph
Gearbox	6 speed Semi-Automatic

# Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	60.1 mpg
Consumption combined	54.3 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/13



## Internet history

### Entry 2

Date 2021-02-03

Pictures 1


Listing price <u>View report</u>



#### source: autoonline.co.uk

#### Entry 1

Date	2021-01-21
Pictures	98











source: yesauto.com

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-12-07
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	20
Total items failed	6

MOT #14	2023-12-08 09:04
MOT test number	959566998875
Result	✓ Passed
Next expiry date	2024-12-07
Advice Protective undertrays fitted	
Advice Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #13	2023-11-30 11:19
MOT test number	171001039594
Result	<b>X</b> Failed
Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
Advice Protective undertrays fitted	
Advice Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #12		2022-11-29 14:45
MOT test	number	187493589862
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Rear heat shield insecure	

CarCheck.co.uk page 3/13



MOT #11 2022-11-28 13:55

**MOT test number** 680322608766

Result X Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Rear heat shield insecure

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10** 2021-12-02 13:42

**MOT test number** 310723947435

Result 

Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9 2020-12-03 16:41

**MOT test number** 724797329769

**Result** ✓ Passed

MOT #8 2019-07-11 15:57

**MOT test number** 277647956894

**Result** ✓ Passed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/13



MOT #7 2019-07-11 09:07

MOT test number 501568071728

**Result** X Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))

MOT #6 2018-07-03 10:06

**MOT test number** 367340142619

**Result** ✓ Passed

MOT #5 2018-07-03 10:06

MOT test number 274689483731

Result X Failed

**Pass with rectification** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #4** 2017-07-08 09:06

MOT test number 822049960440

**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Oil leak

MOT #3 2016-05-28 08:52

**MOT test number** 704851367254

**Result** 
✓ Passed

CarCheck.co.uk page 5/13



MOT #2

MOT test number

Result

Advice
Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice
Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1

2014-06-27 09:57

MOT test number

215068974459

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

CarCheck.co.uk page 6/13



## Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	7 December 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	
********	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NIE NIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-07-15
Last registration	2023-12-08
Complete history	See info



Registration #1	2011-07-15	25 mi
Registration #2	2014-06-27	25.893 mi
Registration #3	2015-06-15	30.124 mi
Registration #4	2016-05-28	36.110 mi
Registration #5	2017-07-08	43.939 mi
Registration #6	2018-07-03	49.576 mi
Registration #7	2018-07-03	49.576 mi
Registration #8	2019-07-11	55.288 mi
Registration #9	2019-07-11	55.288 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		0.777-46

More info >

CarCheck.co.uk page 12/13



## Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



# Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1699 kg
Max. allowed weight	2250 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1:

Number of axles 2

**Engine number** JBER3020728