



report date: 2024-03-29

General information

Make	KIA
Model	SEDONA CRDI LE
Colour	Silver
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	310 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	26.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.2 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-10-20
Pictures	26
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-20
Pictures	26
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #17	2021-10-22 16:03
MOT test number	497512342441
Result	✓ Passed
Next expiry date	2022-10-21

MOT #16	2020-12-19 12:30
MOT test number	699885803093
Result	✓ Passed
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2020-12-14 10:34
MOT test number	431502163531
Result	✗ Failed
Fail	Rear Brakes imbalanced across an axle Delayed effort to offside rear.. (1.2.1 (b) (i))
Fail	Nearside Side repeater not working (4.4.1 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Rear Parking brake inoperative on one side Very low effort to offside rear.. (1.4.1 (a))
Fail	Headlamp aim too low Possible adjuster faulty, lens deteriorated.. (4.1.2 (a))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #14	2019-06-18 14:07
MOT test number	579932853191
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13**

2019-06-17 08:37

MOT test number

781955394524

Result**✗ Failed**

- Advice** Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing also worn on inner edge (5.2.3 (d) (ii))
- Fail** Offside Front Inner Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt split (2.1.3 (g) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge Both side front worn on inner edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12

2018-06-15 09:30

MOT test number

346247976501

Result**✓ Passed**

- Advice** Nearside Front Headlight needs replacing or cleaning beam image not sharp
- Advice** Both front tyres wearing on inner edge

MOT #11

2017-06-17 09:43

MOT test number

831452661792

Result**✓ Passed**

- Advice** Nearside Front TYRE BOLD FROM OUTER EDGE
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #10

2016-06-18 08:08

MOT test number

502305904321

Result**✓ Passed**

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9** 2015-06-12 09:15**MOT test number** 865343065118**Result** ✓ Passed**Notice** Slight lip on front brake discs**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #8** 2014-06-19 13:38**MOT test number** 857230574153**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Play in steering rack inner joint(s)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2014-06-14 09:21**MOT test number** 788915464125**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Play in steering rack inner joint(s)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2013-06-16 11:28**MOT test number** 127697463160**Result** ✓ Passed**Advice** Offside Front Drag link end ball joint has slight play (2.2.B.1f)

**MOT #5** 2012-06-16 11:55**MOT test number** 709398862178**Result** ✓ Passed**Notice** Both front tyres worn inner edges**MOT #4** 2011-06-13 10:51**MOT test number** 586994661178**Result** ✓ Passed**MOT #3** 2011-06-13 10:51**MOT test number** 369214961140**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Offside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**Pass with rectification** Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**MOT #2** 2010-06-17 09:24**MOT test number** 280318460462**Result** ✓ Passed**Notice** Tracking out**MOT #1** 2009-06-13 09:15**MOT test number** 440004069182**Result** ✓ Passed**Advice** Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	RX06LCM
Plate since	2024-03-29
Current registration	RX06LCM
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-06-22
Last registration	2021-10-22
Complete history	See info



Registration #1	2006-06-22	14 mi
Registration #2	2009-06-13	21.066 mi
Registration #3	2010-06-17	28.958 mi
Registration #4	2011-06-13	37.046 mi
Registration #5	2012-06-16	45.111 mi
Registration #6	2013-06-16	50.785 mi
Registration #7	2014-06-14	56.744 mi
Registration #8	2014-06-19	56.780 mi
Registration #9	2015-06-12	64.177 mi
Registration #10	2016-06-18	69.834 mi
Registration #11	2016-06-18	75.491 mi
Registration #12	2016-06-18	81.148 mi
Registration #13	2016-06-18	86.805 mi
Registration #14	2016-06-18	92.462 mi
Registration #15	2016-06-18	98.119 mi
Registration #16	2016-06-18	103.776 mi
Registration #17	2016-06-18	109.433 mi
Registration #18	2016-06-18	115.090 mi
Registration #19	2016-06-18	120.747 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1900 mm
Height	1805 mm
Length	4925 mm
Wheel base	2905 mm
Kerb weight	2220 kg
Max. allowed weight	2738 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	J3725235