



RENAULT

EYIIYXE

report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO ML19 DCI
Colour	White
Year of manufacture	2011
Top speed	91 mph
0 - 60 mph	19.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	185 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	57.6 mpg
Consumption combined	54.3 mpg





Internet history

Entry 1

Date	2022-04-01
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-05
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	21
Total items failed	26

MOT #16	2024-03-06 14:43
MOT test number	914769974464
Result	✓ Passed
Next expiry date	2025-03-05

MOT #15	2024-03-05 13:22
MOT test number	864899011383
Result	✗ Failed

- Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))
- Fail** Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Headlamp light intensity severely reduced (4.1.4 (a))
- Fail** Nearside Front Inner Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #14	2023-01-30 11:21
MOT test number	337298805221
Result	✓ Passed

- Advice** Both rear handbrake cables corroded

**MOT #13**

2022-01-17 15:53

MOT test number

517453771925

Result

✓ Passed

Advice Headlamp has a product on the lens but not seriously reducing light output both front`s (4.1.4 (b))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Play in steering rack inner joint(s)**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #12**

2022-01-17 13:46

MOT test number

109923264817

Result

✗ Failed

Advice Offside Front Play in steering rack inner joint(s)**Advice** Headlamp has a product on the lens but not seriously reducing light output both front`s (4.1.4 (b))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #11**

2020-12-17 12:34

MOT test number

711905248083

Result

✓ Passed



MOT #10	2019-06-13 15:37
----------------	------------------

MOT test number	745759641024
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2019-06-13 08:31
---------------	------------------

MOT test number	312624566810
------------------------	--------------

Result	✗ Failed
---------------	----------

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #8	2018-06-05 14:36
---------------	------------------

MOT test number	551190972416
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #7** 2018-06-05 11:08**MOT test number** 572795287299**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Oil cap ? detached in engine bay**Fail** Brake fluid contaminated (1.8 (a))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Windscreen washer not working (3.5 (a))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))**MOT #6** 2017-06-05 11:27**MOT test number** 168405494193**Result** ✓ Passed

**MOT #5** 2017-06-05 09:14**MOT test number** 713845142841**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #4** 2016-02-02 09:58**MOT test number** 733817245918**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #3** 2016-02-02 09:58**MOT test number** 722523776904**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Pass with rectification** Nearside Windscreen wiper not operating over a large enough area to give an adequate view (8.2.1c)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #2** 2015-01-24 08:37**MOT test number** 927314025092**Result** ✓ Passed



MOT #1	2014-01-30 16:45
MOT test number	159590934012
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
5 March 2025

Tax status		Valid until 1 May
Days left		368
MOT expiry date		5 March 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	EY11YXE
Plate since	2019-09-29
Current registration	EY11YXE
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-31
Last registration	2024-03-06
Complete history	See info



Registration #1	2011-03-31	27 mi
Registration #2	2014-01-30	59.392 mi
Registration #3	2015-01-24	79.714 mi
Registration #4	2016-02-02	88.898 mi
Registration #5	2016-02-02	88.898 mi
Registration #6	2017-06-05	100.171 mi
Registration #7	2017-06-05	100.175 mi
Registration #8	2018-06-05	108.082 mi
Registration #9	2018-06-05	108.084 mi
Registration #10	2019-06-05	115.277 mi
Registration #11	2019-06-05	115.277 mi
Registration #12	2019-06-05	115.277 mi
Registration #13	2019-06-05	115.277 mi
Registration #14	2019-06-05	115.277 mi
Registration #15	2019-06-05	115.277 mi
Registration #16	2019-06-05	115.277 mi
Registration #17	2019-06-05	115.277 mi
Registration #18	2019-06-05	115.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	D096644