





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	ML ML250 BLUETEC SE
Colour	Grey
Year of manufacture	2013
Top speed	130 mph
0 - 100 km/h	9.0 seconds
0 - 60 mph	9.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	150 kW / 204 HP / 204 BHP
Max. torque	500 Nm at 1.800 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.8 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-11
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	15
Total items failed	5

MOT #10	2024-03-12 17:22
MOT test number	987589560656
Result	✓ Passed
Next expiry date	2025-03-11
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	14 (a) (ii))
Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1	.14 (a) (ii))

MOT #9		2023-03-09 15:51
MOT test	number	777626477771
Result		✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply o	r cords (5.2.3 (d) (i))

MOT #8	2022-01-29 15:15
MOT test number	200140911075
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #7 2021-02-01 11:51

MOT test number 634433125638

MOT #6 2020-11-17 19:09

MOT test number 502161403118

Result

Passed

Advice Oil leak, but not excessive Transfer box area. (8.4.1 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2020-11-12 07:51

MOT test number 483723802034

Result X Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Oil leak, but not excessive transfer box (8.4.1 (a) (i))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2020-11-12 07:45

MOT test number 189976734789

Result X Failed

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Oil leak, but not excessive transfer box (8.4.1 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 4/12



MOT test number

Result

Advice
Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1)

Advice
Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice
Offside Front Outer Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2016-12-23 10:13
MOT test number	376528543836
Result	✓ Passed
MOT #1	2015-12-29 10:23
MOT test number	831621761450
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	11 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

,	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How may MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

Plate changes	More info >
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-01-02
Last registration	2024-03-12
Complete history	See info



Registration #1	2013-01-02	26 mi
Registration #2	2015-12-29	38.290 mi
Registration #3	2016-12-23	44.083 mi
Registration #4	2017-12-20	50.393 mi
Registration #5	2020-11-12	55.874 mi
Registration #6	2020-11-12	55.873 mi
Registration #7		11.777 ms
Registration #8		77,777 46
Registration #9		11.777 mi
Registration #10		77,777 66
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0295	
50482	
60501	
60566	
60567	
60569	

Dimensions & weight

Width	1998 mm
Height	1796 mm
Length	4804 mm
Wheel base	2915 mm
Kerb weight	2150 kg
Max. allowed weight	2950 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	65196031474778

CarCheck.co.uk page 12/12