



report date: 2024-03-29

General information

Make	NISSAN
Model	NV200 DCI SE
Colour	Grey
Year of manufacture	-
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	54.3 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-13
Pictures	10
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #14	2023-01-11 16:02
MOT test number	324358734412
Result	✓ Passed
Next expiry date	2024-01-10

MOT #13	2022-01-10 15:55
MOT test number	299896943807
Result	✓ Passed

MOT #12	2022-01-07 12:27
MOT test number	258875940820
Result	✗ Failed

Fail Rear Upper Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #11	2020-12-04 11:42
MOT test number	430501282890
Result	✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2019-11-07 13:37
MOT test number	180809594323
Result	✓ Passed

MOT #9	2019-09-07 11:43
MOT test number	434130935448
Result	✓ Passed

**MOT #8**

2018-09-25 11:11

MOT test number

327165443742

Result

✓ Passed

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #7**

2017-09-27 10:44

MOT test number

728380681216

Result

✓ Passed

Advice Offside Front Seat belt damaged but webbing not significantly weakened seat belt webbing slight damage (5.2.2a)**Advice** Offside Rear sliding door does not open**Advice** Offside Front Direction indicator slightly discoloured pale in colour (1.4.A.2f)**MOT #6**

2016-07-22 15:42

MOT test number

479821007756

Result

✓ Passed

Advice Offside Rear Leaf spring has a slightly deteriorated shackle pin rubber bush not resulting in excessive movement (2.4.B.2)**Advice** Nearside Rear Leaf spring has a slightly deteriorated shackle pin rubber bush not resulting in excessive movement (2.4.B.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2016-07-22 15:42**MOT test number** 121865367472**Result** ✗ Failed**Advice** Nearside Rear Leaf spring has a slightly deteriorated shackle pin rubber bush not resulting in excessive movement (2.4.B.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Leaf spring has a slightly deteriorated shackle pin rubber bush not resulting in excessive movement (2.4.B.2)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #4** 2015-07-04 10:18**MOT test number** 158515785140**Result** ✓ Passed**MOT #3** 2015-07-04 10:18**MOT test number** 378955785182**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2014-07-07 16:27**MOT test number** 785648284167**Result** ✓ Passed



MOT #12014-07-04 15:00

MOT test number899185584195

ResultX Failed

- Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail

Rear Registration plate lamp not working (1.1.C.1d)
- Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	FH11HHJ
Plate since	2019-09-29
Current registration	FH11HHJ
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-07-29
Last registration	2023-01-11
Complete history	See info



Registration #1	2011-07-29	19 mi
Registration #2	2014-07-04	96.025 mi
Registration #3	2014-07-07	96.140 mi
Registration #4	2015-07-04	126.320 mi
Registration #5	2016-07-22	136.439 mi
Registration #6	2016-07-22	136.439 mi
Registration #7	2017-09-27	139.312 mi
Registration #8	2018-09-25	143.254 mi
Registration #9	2019-05-29	151.277 mi
Registration #10	2019-05-29	151.277 mi
Registration #11	2019-05-29	151.277 mi
Registration #12	2019-05-29	151.277 mi
Registration #13	2019-05-29	151.277 mi
Registration #14	2019-05-29	151.277 mi
Registration #15	2019-05-29	151.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1695 mm
Height	1860 mm
Length	4400 mm
Wheel base	2725 mm
Kerb weight	1269 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	083830