





report date: 2024-03-28

General information

Make	JAGUAR
Model	XJ TDVI SOVEREIGN LWB
Colour	Blue
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	204 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.9 mpg
CO2 emission	214 g/km
CO2 label	K



CarCheck.co.uk page 1/15



report date: 2024-03-28


Internet history

Entry 2


Date 2021-07-31

Pictures 33

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 1

Date	2021-07-10
Pictures	7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-05
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	37
Total items failed	20

MOT #22	2024-03-26 12:07
MOT test number	111352208924
Result	✓ Passed
Next expiry date	2025-04-05
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Washer bottle is leaking	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Nearside Front Outer Track rod end ball joint dust cover damaged or deterior the ingress of dirt (2.1.3 (g) (i))	rated, but preventing
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #21	2023-04-05 09:43
MOT test number	596134480156
Result	✓ Passed

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT test number

Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Track rod ends corroded

Advice Front Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #19 2022-03-31 15:51 **MOT** test number 410664704196 Result × Failed **Advice** Rear Brake pipe corroded, covered in grease or other material Both sides (1.1.11 (c)) **Advice** Front Track rod ends corroded Advice Nearside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Fail Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i)) Advice Front Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Offside Rear Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) Rear suspension arm pin/bush boots split both sides **Advice** Fail Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i)) **Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #18	2021-03-23 10:01
MOT test number	965094838402
Result	✓ Passed
Advice Offside Front Tyre slightly damaged/cracking or perishing started perishing outer tread 255/40/19 (5.2.3 (d) (ii))	

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #17 2020-03-18 13:16

MOT test number 385070501564

MOT #16 2020-03-17 16:06

MOT test number 176274766550

Result X Failed

Fail Offside Rear Suspension rod ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Rear Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Rear Suspension rod ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Rear Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #15 2019-03-26 14:27

MOT test number 950674649659

Result \(\sqrt{Passed} \)

MOT #14 2019-03-26 10:17

MOT test number 266668807524

Result × Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #13 2018-04-05 10:53

MOT test number 854941851010

Result ✓ Passed

MOT #12 2017-05-05 08:51

MOT test number 216939593058

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #11	2016-05-20 09:28
MOT test number	169482118851
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #10	2015-06-26 15:53
MOT test number	649247875105
Result	✓ Passed
MOT #9	2015-06-19 15:00
MOT test number	256410575104
Result	× Failed
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	

MOT #8		2014-07-21 14:22
MOT test	number	597722504212
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	O/s/f tyre has slight damage to sidewall	
Notice	Under-trays fitted obscuring some underside components	
Notice	O/s/f tyre starting to deterioate	
Notice	N/s/f tyre has slight damage to sidewall	
Notice	N/s wiper split	

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #7 2014-07-21 12:31 809312104206 **MOT** test number × Failed Result **Notice** O/s/f tyre starting to deterioate Fail Windscreen washer provides insufficient washer liquid (8.2.3) Notice N/s wiper split Notice Engine covers fitted obscuring some components in the engine bay Notice O/s/f tyre has slight damage to sidewall Notice Under-trays fitted obscuring some underside components

 MOT #6
 2013-07-31 10:53

 MOT test number
 969882213222

 Result
 ✓ Passed

 MOT #5
 2012-09-11 12:20

 MOT test number
 139925552218

 Result
 ✓ Passed

MOT #4

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Headlamp not working on dipped beam (1.7.5a)

Fail Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Advice

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2

MOT test number

Result

MOT #1

MOT test number

2010-04-16 14:24

782116500103

Passed

MOT #1

862923300164

Result × Failed Fail Offside Body has a sharp edge caused by damage (6.1.C.1) Fail Front brakes release unevenly (3.7.B.4) Fail Rear brakes release unevenly (3.7.B.4) Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b) Fail Front brake application uneven (3.7.B.2) Fail Rear brake application uneven (3.7.B.2) Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Fail (4.1.D.1a)

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	5 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



factor scincol

ST07TOG

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this JAGUAR had different number plates. abser of plantes

CarCheck.co.uk page 12/15



ST07TOG report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-04-17
Last registration	2024-03-26
Complete history	See info



Registration #2 2010-04-13 36.758 Registration #3 2010-04-16 36.758 Registration #4 2011-07-09 46.689 Registration #5 2012-09-07 47.877 Registration #6 2012-09-11 47.877 Registration #7 2013-07-31 49.285 Registration #8 2014-07-21 50.617 Registration #9 2014-07-21 50.617 Registration #10 2015-06-19 51.213 Registration #11 2015-06-26 51.270 Registration #12 2016-05-20 63.611 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21 Registration #21 Registration #22 Registration #21 Registration #21 Registration #22			
Registration #3 2010-04-16 36.758 Registration #4 2011-07-09 46.689 Registration #5 2012-09-07 47.877 Registration #6 2012-09-11 47.877 Registration #7 2013-07-31 49.285 Registration #8 2014-07-21 50.617 Registration #9 2014-07-21 50.617 Registration #10 2015-06-19 51.213 Registration #11 2015-06-26 51.270 Registration #12 2016-05-20 63.611 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #21 Registration #22	Registration #1	2007-04-17	28 mi
Registration #4 2011-07-09 46.689 f Registration #5 2012-09-07 47.877 f Registration #6 2012-09-11 47.877 f Registration #7 2013-07-31 49.285 f Registration #8 2014-07-21 50.617 f Registration #9 2014-07-21 50.617 f Registration #10 2015-06-19 51.213 f Registration #11 2015-06-26 51.270 f Registration #12 2016-05-20 63.611 f Registration #13 f Registration #14 f Registration #15 f Registration #16 f Registration #17 f Registration #18 f Registration #19 f Registration #20 f Registration #21 f Registration #21 f Registration #22 f Registrat	Registration #2	2010-04-13	36.758 mi
Registration #5 2012-09-07 47.877 Registration #6 2012-09-11 47.877 Registration #7 2013-07-31 49.285 Registration #8 2014-07-21 50.617 Registration #9 2014-07-21 50.617 Registration #10 2015-06-19 51.213 Registration #11 2015-06-26 51.270 Registration #12 2016-05-20 63.611 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22 Reg	Registration #3	2010-04-16	36.758 mi
Registration #6 2012-09-11 47.877 f Registration #7 2013-07-31 49.285 f Registration #8 2014-07-21 50.617 f Registration #9 2014-07-21 50.617 f Registration #10 2015-06-19 51.213 f Registration #11 2015-06-26 51.270 f Registration #12 2016-05-20 63.611 f Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #4	2011-07-09	46.689 mi
Registration #7 Registration #8 2014-07-21 50.617 ft Registration #9 2014-07-21 50.617 ft Registration #10 2015-06-19 Registration #11 2015-06-26 51.270 ft Registration #12 2016-05-20 63.611 ft Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21 Registration #22	Registration #5	2012-09-07	47.877 mi
Registration #8 2014-07-21 50.617 m Registration #9 2014-07-21 50.617 m Registration #10 2015-06-19 51.213 m Registration #11 2015-06-26 51.270 m Registration #12 2016-05-20 63.611 m Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21	Registration #6	2012-09-11	47.877 mi
Registration #9 2014-07-21 50.617 m Registration #10 2015-06-19 51.213 m Registration #11 2015-06-26 51.270 m Registration #12 2016-05-20 63.611 m Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #7	2013-07-31	49.285 mi
Registration #10 2015-06-19 51.213 m Registration #11 2015-06-26 51.270 m Registration #12 2016-05-20 63.611 m Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21	Registration #8	2014-07-21	50.617 mi
Registration #11 2015-06-26 51.270 r Registration #12 2016-05-20 63.611 r Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21	Registration #9	2014-07-21	50.617 mi
Registration #12 2016-05-20 63.611 registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #10	2015-06-19	51.213 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #11	2015-06-26	51.270 mi
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #12	2016-05-20	63.611 mi
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21	Registration #13		11.777 es
Registration #15 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #14		11.117 au
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #15		11.777 es
Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #16		11.117 au
Registration #19 Registration #20 Registration #21 Registration #22	Registration #17		11.777 es
Registration #20 Registration #21 Registration #22	Registration #18		11.777 es
Registration #21 Registration #22	Registration #19		11.777 es
Registration #22	Registration #20		11.177 es
-	Registration #21		11.777 es
Pagistration #23	Registration #22		11.777 es
Registration #25	Registration #23		11.777 mi

More info >

CarCheck.co.uk page 14/15



ST07TOG
report date: 2024-03-28

		_	
Dume	nciona	- J.	Woldht
	נווטוכוו:	o CX	weight

Width	1898 mm
Height	1455 mm
Length	5215 mm
Wheel base	3159 mm
Kerb weight	1659 kg
Max. allowed weight	2306 kg

Additional information

Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	02230647G

CarCheck.co.uk page 15/15