



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2300 L2H1 CDTI S/S ECOFLEX
Colour	Silver
Year of manufacture	2015
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.6 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-01-16
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-03-07
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	15
Total items failed	1

MOT #8	2023-03-08 10:15
MOT test number	900649676708
Result	✓ Passed
Next expiry date	2024-03-07
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7	2023-03-08 10:15
MOT test number	684435984308
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2022-02-15 13:58
MOT test number	799914011142
Result	✓ Passed
Minor	Rear Registration plate lamp insecure (4.7.1 (c) (i))

**MOT #5** 2021-06-25 14:25**MOT test number** 411102422823**Result** ✓ Passed**MOT #4** 2020-07-24 10:57**MOT test number** 520393780779**Result** ✓ Passed**MOT #3** 2019-10-21 08:40**MOT test number** 407113868428**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2018-10-24 09:11**MOT test number** 138380065585**Result** ✓ Passed**Advice** Offside Front lower mirror missing**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #1** 2018-10-24 09:02**MOT test number** 290400844102**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front lower mirror missing**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Brake pedal anti-slip provision missing (1.1.2 (c))



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VAUXH
Plate since	2024-03-29
Current registration	 VAUXH
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-11-25
Last registration	2023-03-08
Complete history	See info



Registration #1	2015-11-25	14 mi
Registration #2	2018-10-24	29.245 mi
Registration #3	2018-10-24	29.245 mi
Registration #4	2019-10-21	55.286 mi
Registration #5	2020-07-24	60.085 mi
Registration #6	2020-07-24	60.085 mi
Registration #7	2020-07-24	60.085 mi
Registration #8	2020-07-24	60.085 mi
Registration #9	2020-07-24	60.085 mi
Registration #10	2020-07-24	60.085 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1880 mm
Length	4740 mm
Kerb weight	1330 kg
Max. allowed weight	2385 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005486430 LN9