

Ford



General information

Make	FORD
Model	KA ZETEC
Colour	Black
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP	
Max. torque	102 Nm at 3.000 rpm	
Engine capacity	1.242 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	44.8 mpg	
Consumption extra urban	64.2 mpg	
Consumption combined	55.4 mpg	
CO2 emission	119 g/km	
CO2 label	С	





MOT history

MOT expiry date	2025-01-12
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	21
Total items failed	7

MOT #15		2024-01-12 09:31
MOT test numb	ber	287328044709
Result		✓ Passed
Next expiry da	te	2025-01-12
Advice Coil	spring corroded ALL 4 (5.3.1 (b) (i))	
Advice Rea	Axle deformed but serviceable (5.1.1 (a))	
Advice From	t Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #14 2024-01-12 09:31 203812822187 **MOT test number** Result × Failed Rear Axle deformed but serviceable (5.1.1 (a)) Advice Pass with rectification Rear Shock absorbers has an excessively worn bush BOTH SIDE (5.3.2 (c)) Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) Advice Coil spring corroded ALL 4 (5.3.1 (b) (i)) Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))





MOT #13	2023-01-11 14:37
MOT test number	630912072831
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored	d, but not seriously weakened Both (1.1.14 (a) (ii))
MOT #12	2022-01-12 16:24
MOT test number	840313310294
Result	✓ Passed
MOT #11	2021-01-13 15:01
MOT test number	316673645122
Result	✓ Passed
MOT #10	2021-01-13 15:01
MOT test number	213272066885
Result	× Failed
Pass with rectificationRegistration plate land(4.7.1 (b) (ii))	mp inoperative in the case of a single lamp or all lamps
MOT #9	2019-11-26 10:50
MOT test number	168549406324
Result	✓ Passed
МОТ #8	2019-01-03 16:54
MOT test number	205806628218
Result	✓ Passed
Advice Offside Rear light lens cracked/damag	ed





MOT #7	2019-01-02 11:29
MOT test number	623393925725
Result	🗙 Failed
FailNearside Rear Registration plate lamp inoperative in the case of a single lamp or a(ii))	II lamps (4.7.1 (b)
Advice Offside Rear light lens cracked/damaged	
Fail Offside Front Headlamp insecure brackets broken (4.1.1 (c))	
Advice Nearside Rear Shock absorbers has a slightly worn bush slight play (5.3.2 (c))	
Fail Nearside Front Headlamp insecure brackets broken (4.1.1 (c))	
Advice Offside Front Road wheel slightly distorted inner (5.2.2 (c) (i))	
Advice Offside Rear Shock absorbers has a slightly worn bush slight play (5.3.2 (c))	

MOT #6		2017-12-12 17:02
MOT test	number	732383353807
Result		Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #5	2017-12-12 08:55
MOT test number	915684433982
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #4	2016-11-30 11:37
MOT test number	598433152163
Result	✓ Passed
MOT #3	2015-12-08 09:20
MOT test number	956063702929
Result	✓ Passed
MOT #2	2014-12-12 11:07
MOT test number	648956344391
Result	✓ Passed
MOT #1	2013-12-11 09:23
MOT test number	255345143305
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 November 2024	✓ MOT Expires: 12 January 2025
Tax status	Valid until 1 November
Days left	186
MOT expiry date	12 January 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



EK60YKW report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-10-16
Last registration	2024-01-12
Complete history	See info



Registration #1	2010-10-16	14 mi
Registration #2	2013-12-11	24.732 mi
Registration #3	2014-12-12	32.904 mi
Registration #4	2015-12-08	39.278 mi
Registration #5	2016-11-30	48.524 mi
Registration #6	2017-12-12	54.798 mi
Registration #7	2017-12-12	54.798 mi
Registration #8	2019-01-02	64.550 mi
Registration #9	8555-25-27	11.777 esi
-	80003-203-20 80003-20-20	11.227 est
Registration #9	8000-20-20 8000-20-20 8000-20-20	01.000 est 01.000 est 01.000 est
Registration #9 Registration #10	80003-203-20 80003-203-20 80003-203-20 80003-203-20	00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11	10005-205-20 10005-205-20 10005-205-20 10005-205-20	00.000 est 0.000 est 00.000 est 0.000 est 00.000 est
Registration #9 Registration #10 Registration #11 Registration #12	8000-20-20 8000-20-20 8000-20-20 8000-20-20 8000-20-20	00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10 Registration #11 Registration #12 Registration #13	1000 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0	00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460

More info >





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg
Additional information	
Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	5775203