





report date: 2024-03-29

## General information

Make	MINI
Model	COUNTRYMAN COOPER SD ALL4 AUTO COOPER SD ALL4
Colour	White
Year of manufacture	2012
Top speed	120 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G



CarCheck.co.uk page 1/12




## Internet history

#### Entry 2


Date 2023-01-29


Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-05-22
-----------------

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-06
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #11	2023-09-07 10:01
MOT test number	130249172034
Result	✓ Passed
Next expiry date	2024-09-06

MOT #10	2022-08-30 12:31
MOT test number	884022931119
Result	✓ Passed

MOT #9	2021-05-25 12:29
MOT test number	285998084951
Result	<b>✓</b> Passed

MOT #8	2021-05-25 12:29
MOT test number	145003545375

Result X Failed

Pass with rectification Front Tyre tread depth below requirements of 1.6mm X2 (5.2.3 (e))

CarCheck.co.uk page 3/12



**GY62KCC** 

report date: 2024-03-29

MOT test number

625726966225

Result

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT** #6 2020-07-15 13:41 **MOT** test number 366993309772 Result × Failed Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) Fail Offside Rear Coil spring corroded (5.3.1 (b) (i)) Advice Advice Offside Rear Nail in tyre Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #5	2019-08-07 14:40
MOT test number	288440104124
Result	✓ Passed

MOT #4	2018-05-23 12:54
MOT test number	162443071190
Result	<b>✓</b> Passed
Advice Undercovers fitted	

CarCheck.co.uk page 4/12



MOT #3	2017-05-22 11:07
MOT test number	593055436594
Result	<b>✓</b> Passed
MOT #2	2016-06-07 12:56
MOT test number	993971426251
Result	<b>✓</b> Passed
MOT #1	2015-06-01 16:31
MOT test number	167712655147
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	6 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



GY62KCC

report date: 2024-03-29

#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



O	l- ! - 4
UWNER	nistorv
Owner	ilistoi y

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
**************************************	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK ZIS
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-28
Last registration	2023-09-07
Complete history	See info



Registration #1	2012-09-28	15 mi
Registration #2	2015-06-01	26.333 mi
Registration #3	2016-06-07	34.619 mi
Registration #4	2017-05-22	39.109 mi
Registration #5	2018-05-23	50.469 mi
Registration #6	2019-08-07	60.815 mi
Registration #7	2020-07-15	66.343 mi
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1420 kg
Max. allowed weight	1880 kg

# Additional information

Fuel tank capacity	47 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12