





report date: 2024-03-29

#### General information

Make	BMW
Model	125 420D M SPORT
Colour	Blue
Year of manufacture	2015
Top speed	142 mph
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/11



#### Internet history

#### Entry 2

Date 2022-11-01

Pictures 32

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date 2022-01-13

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-15
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	2
Total items failed	2

MOT #8	2023-10-04 14:32
MOT test number	934739053694
Result	✓ Passed
Next expiry date	2024-10-15
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #7	2023-10-04 10:02
MOT test number	836104926014
Result	<b>X</b> Failed
Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2022-10-15 14:49
MOT test number	138812226021
Result	<b>✓</b> Passed
MOT #5	2021-10-16 10:18
MOT test number	657788691753
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



MOT #4 2020-10-02 07:49 **MOT test number** 790606748382 ✓ Passed Result MOT #3 2019-03-25 12:53 932275809524 **MOT test number** Result ✓ Passed MOT #2 2019-03-18 14:43 245475746404 **MOT test number** Result × Failed Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #1	2018-04-07 08:06
MOT test number	509764945928
Result	✓ Passed

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	15 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category



#### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



## Owner history

For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>has</u>	
manus .	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK SIE
Flate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-20
Last registration	2023-10-04
Complete history	See info



Registration #1	2015-03-20	28 mi
Registration #2	2018-04-07	15.566 mi
Registration #3	2019-03-18	25.268 mi
Registration #4	2019-03-25	25.404 mi
Registration #5	2020-10-02	38.795 mi
Registration #6	2021-10-16	47.830 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



## Dimensions & weight

Width	1825 mm
Height	1384 mm
Length	4638 mm
Wheel base	2810 mm
Kerb weight	1715 kg
Max. allowed weight	2185 kg

# Additional information

Fuel tank capacity	57 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	4	page 11/11

Number of axles 2
Engine number 70179342