



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D5 SE LUX
Colour	Silver
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 2


Date	2021-11-13
Pictures	23
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-07
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-07
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #16	2023-06-08 08:30
MOT test number	440204114828
Result	✓ Passed
Next expiry date	2024-06-07
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Exhaust mounting defective (6.1.2 (a))

MOT #15	2022-06-08 08:51
MOT test number	675217564427
Result	✓ Passed

MOT #14	2021-06-07 10:39
MOT test number	283694901170
Result	✓ Passed

MOT #13	2020-10-06 11:24
MOT test number	832740105101
Result	✓ Passed

**MOT #12** 2019-10-01 15:43**MOT test number** 464798117212**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2019-10-01 09:31**MOT test number** 640801872059**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-09-25 12:45**MOT test number** 552842765037**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2017-10-04 14:30**MOT test number** 264127381967**Result** ✓ Passed**MOT #8** 2017-10-04 08:45**MOT test number** 636688871935**Result** ✗ Failed**Advice** Nearside Front Inner Tyre worn close to the legal limit very low (4.1.E.1)**Fail** Offside Front Inner Tyre has ply or cords exposed (4.1.D.1b)



MOT #7	2016-10-10 11:26
---------------	------------------

MOT test number	847893562055
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2015-10-14 09:28
---------------	------------------

MOT test number	530411074694
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2014-10-13 09:28
---------------	------------------

MOT test number	288056884205
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2013-10-07 12:43
---------------	------------------

MOT test number	398040283274
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2012-10-01 10:33
---------------	------------------

MOT test number	219015272205
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	-----------------------------------------------------------

Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	------------------------------------------------------------

MOT #2	2011-09-30 17:17
---------------	------------------

MOT test number	126253671212
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2010-10-09 09:13
---------------	------------------

MOT test number	260522680276
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
7 June 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	7 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	OV57RUW
Plate since	2019-09-28
Current registration	OV57RUW
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-10-24
Last registration	2023-06-08
Complete history	See info



Registration #1	2007-10-24	10 mi
Registration #2	2010-10-09	37.490 mi
Registration #3	2011-09-30	46.428 mi
Registration #4	2012-10-01	55.656 mi
Registration #5	2013-10-07	63.283 mi
Registration #6	2014-10-13	71.036 mi
Registration #7	2015-10-14	79.845 mi
Registration #8	2016-10-10	89.173 mi
Registration #9	2017-10-04	98.836 mi
Registration #10	2017-10-04	98.836 mi
Registration #11	2018-10-04	108.500 mi
Registration #12	2019-10-04	118.163 mi
Registration #13	2020-10-04	127.826 mi
Registration #14	2021-10-04	137.489 mi
Registration #15	2022-10-04	147.152 mi
Registration #16	2023-06-08	156.815 mi
Registration #17	2023-06-08	156.815 mi
Registration #18	2023-06-08	156.815 mi
Registration #19	2023-06-08	156.815 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1757 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	541485