



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VALVEMATIC T SPIRIT
Colour	Blue
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	10.4 seconds
Gearbox	7 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-09-14
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-14
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	50
Total items failed	12

MOT #18	2024-02-02 08:55
---------	------------------

MOT test number	148722034797
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-14
------------------	------------

- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor

Headlamp lens slightly defective NSF and OSF (4.1.1 (b) (i))
- Advice

Nearside Rear Seat belt buckle slightly damaged Plastic surround missing. (7.1.2 (d))
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material Corroded. (1.1.11 (c))
- Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Exhaust mounting defective Centre exhaust mount broken. (6.1.2 (a))

**MOT #17**

2024-01-25 11:40

**MOT test number**

610174899498

**Result**

✗ Failed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Corroded. (1.1.11 (c))
- Advice** Nearside Rear Seat belt buckle slightly damaged Plastic surround missing. (7.1.2 (d))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust mounting defective Centre exhaust mount broken. (6.1.2 (a))
- Minor** Headlamp lens slightly defective NSF and OSF (4.1.1 (b) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Front Windscreen washer not working (3.5 (a))

**MOT #16**

2023-02-07 16:05

**MOT test number**

482939905654

**Result**

✓ Passed

**MOT #15**

2022-02-14 15:06

**MOT test number**

222253282875

**Result**

✓ Passed

- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Rear axle corroded
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive both rear chassis legs (5.3.6 (a) (i))
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive both rear inner sills, suspect worse under covers (5.3.6 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Suspension component mounting prescribed area is corroded but not considered excessive both rear axle mounts (5.3.6 (a) (i))

**MOT #14**

2022-02-09 13:30

**MOT test number**

906845880611

**Result****✗ Failed**

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Suspension component mounting prescribed area is corroded but not considered excessive both rear chassis legs (5.3.6 (a) (i))

**Advice** Suspension component mounting prescribed area is corroded but not considered excessive both rear inner sills, suspect worse under covers (5.3.6 (a) (i))

**Fail** Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))

**Advice** Rear axle corroded

**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Suspension component mounting prescribed area is corroded but not considered excessive both rear axle mounts (5.3.6 (a) (i))

**Fail** Rear Suspension component corroded and seriously weakened strengthening brace between axle mounting points (5.3.3 (b) (i))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13**

2021-02-15 11:10

**MOT test number**

814403094559

**Result****✓ Passed**

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12**

2021-02-15 11:10

**MOT test number**

887850911371

**Result****✗ Failed**

**Pass with rectification**

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Pass with rectification**

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Minor**

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11** 2020-02-12 18:03**MOT test number** 316369391881**Result** ✓ Passed**MOT #10** 2019-02-05 18:02**MOT test number** 137338057418**Result** ✓ Passed**MOT #9** 2018-11-27 09:38**MOT test number** 117916627927**Result** ✗ Failed

**Fail** Central Seat belt installation has a claw type seat mounting with an inadequate means of securing the claw (10.1 (o))

**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))

**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #8** 2017-11-21 09:46**MOT test number** 672103552946**Result** ✓ Passed

**Advice** Unable to test rear seat belt buckles

**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**Advice** Rear seats not in the upright position

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Engine light on

**MOT #7** 2017-11-21 09:46**MOT test number** 580149695584**Result** ✗ Failed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Unable to test rear seat belt buckles**Pass with rectification** Direction indicator incorrect colour both rear (1.4.A.2f)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear seats not in the upright position**Advice** Engine light on**MOT #6** 2016-11-02 10:04**MOT test number** 646804087830**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured both side (1.4.A.2f)**Advice** Nearside Rear Body has slight corrosion (6.1.B.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-10-31 10:25**MOT test number** 332342234040**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured both (1.4.A.2f)**Advice** Parking brake lever has little reserve travel (3.1.6b)



**MOT #4** 2014-09-12 10:42**MOT test number** 648005654202**Result** ✓ Passed**MOT #3** 2013-09-12 11:09**MOT test number** 905815253279**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-09-12 11:09**MOT test number** 515985453250**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-09-25 11:46**MOT test number** 425819562264**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 February 2024

✓

MOT

Expires:  
14 February 2025

Tax status	Expired at 1 February 2024
Days left	89 days too late
MOT expiry date	14 February 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>GJ59ADO</b>
Plate since	2019-03-29
Current registration	<b>GJ59ADO</b>
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-30
Last registration	2024-02-02
Complete history	<a href="#">See info</a>



Registration #1	2009-09-30	18 mi
Registration #2	2012-09-25	31.107 mi
Registration #3	2013-09-12	41.388 mi
Registration #4	2014-09-12	48.902 mi
Registration #5	2015-10-31	61.017 mi
Registration #6	2016-11-02	75.035 mi
Registration #7	2017-11-21	84.843 mi
Registration #8	2017-11-21	84.843 mi
Registration #9	2018-11-27	90.618 mi
Registration #10	2019-02-05	90.642 mi
Registration #11	2019-05-20	91.277 mi
Registration #12	2019-05-20	91.277 mi
Registration #13	2019-05-20	91.277 mi
Registration #14	2019-05-20	91.277 mi
Registration #15	2019-05-20	91.277 mi
Registration #16	2019-05-20	91.277 mi
Registration #17	2019-05-20	91.277 mi
Registration #18	2019-05-20	91.277 mi
Registration #19	2019-05-20	91.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1630 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2



Engine number	2ZFU215118
---------------	------------