





General information

Make	NISSAN
Model	PATHFINDER DCI MAMMOTH
Colour	Grey
Year of manufacture	2008
Top speed	108 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	169 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	32.5 mpg
Consumption combined	27.7 mpg
CO2 emission	276 g/km
CO2 label	М





Internet history

Entry 1

Date Pictures 2021-09-03

19

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-14
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	6
Total items failed	13

MOT #17	2023-09-12 15:31
MOT test number	848517688766
Result	✓ Passed
Next expiry date	2024-09-14

MOT #16	2022-08-25 11:03
MOT test number	908134693654
Result	✓ Passed
Advice Vehicle structure is corroded but structu	ral rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #15	2021-09-15 10:52
MOT test number	458988777476
Result	✓ Passed

MOT #3	14 202	21-09-13 10:27
MOT te	st number 7	795071146471
Result		🗙 Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail Front Lower Suspension component ball joint excessively worn o/s and n/s (5.3.4 (a) (i))		





MOT #13	2020-08-04 15:30
MOT test number	436406707162
Result	✓ Passed
Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
MOT #12	2020-08-04 14:27
MOT test number	642463425066
Result	🗙 Failed
Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
FailOffside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #11	2019-08-19 13:10
MOT test number	492867243315
Result	✓ Passed

MOT #10	2019-08-19 11:43
MOT test number	410614458306
Result	🗙 Failed
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Fail Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))	

МОТ #9	2018-05-15 07:28
MOT test number	102046258231
Result	✓ Passed



🗙 Failed



MOT #8	2016-08-04 09:51
MOT test number	512367513603
Result	✓ Passed
MOT #7	2015-07-17 15:13
MOT test number	986048795172
Result	✓ Passed
MOT #6	2015-07-17 15:13
MOT test number	618988095178

Result

Pass with rectification

Nearside Stop lamp not working (1.2.1b)

MOT #5	2014-07-29 16:07
MOT test number	987870814211
Result	✓ Passed

МОТ #4	2014-07-29 16:07	
MOT test number	716030214231	
Result	× Failed	
Pass with rectification	Nearside Stop lamp not working (1.2.1b)	
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Pass with rectification lamp (1.1.A.3f)	cation Nearside Rear position lamp(s) adversely affected by the operation of another	
Pass with rectification	Nearside Headlamp aim too low (1.8)	

MOT #3	2013-04-22 16:38
MOT test number	827162713195
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #2	2012-09-10 13:20
MOT test number	927504252297
Result	✓ Passed
MOT #1	2011-09-19 16:49
MOT test number	337662561223
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

Taxed Tax due: 1 September 2024	MOT Expires: 14 September 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	14 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Μ
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-12-03
Last registration	2023-09-12
Complete history	<u>See info</u>



Registration #1	2008-12-03	23 mi
Registration #2	2011-09-19	19.770 mi
Registration #3	2012-09-10	22.876 mi
Registration #4	2013-04-22	25.513 mi
Registration #5	2014-07-29	32.623 mi
Registration #6	2015-07-17	40.816 mi
Registration #7	2016-08-04	49.343 mi
Registration #8	2018-05-15	61.191 mi
Registration #9	2019-08-19	66.316 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.117 esi

More info \rightarrow





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
\$0567	
S0569	

Safety ratings

Number of axles CarCheck.co.uk

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1850 mm
Height	1865 mm
Length	4740 mm
Wheel base	2850 mm
Max. allowed weight	2880 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

2

Engine number

YD25-950843