



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SPORT
Colour	Silver
Year of manufacture	2008
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption


Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1	
Date	2021-10-06
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-18
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	15
Total items failed	3

MOT #15 2023-10-19 09:50

MOT test number 251880513063

Result ✓ Passed

Next expiry date 2024-10-18

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Rear Tyre slightly damaged/cracking or perishing both rear tyres (5.2.3 (d) (ii))

Advice Front Power steering pipe/hose slightly corroded centre pipe next to rack (2.1.5 (g) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #14 2022-09-21 09:36

MOT test number 872303837326

Result ✓ Passed

MOT #13 2021-09-14 09:45

MOT test number 165342156227

Result ✓ Passed

Advice Nearside Rear Seat belt flexible stalk damaged (7.1.2 (b) (i))

**MOT #12** 2020-09-17 10:24**MOT test number** 759106881632**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2019-09-26 08:30**MOT test number** 714352812795**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2018-09-15 11:43**MOT test number** 364065656883**Result** ✓ Passed**MOT #9** 2017-09-12 09:15**MOT test number** 815373617746**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2016-09-28 15:13**MOT test number** 238214894294**Result** ✓ Passed

**MOT #7** 2016-09-28 08:43**MOT test number** 593363545540**Result** ✗ Failed**Advice** Nearside Front tyre has outer side wall damage advise replacement**Advice** Offside Rear tyre poor tread advise replacement**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear tyre has a nail**MOT #6** 2015-09-24 09:42**MOT test number** 818285596426**Result** ✓ Passed**MOT #5** 2014-09-08 14:42**MOT test number** 167661054293**Result** ✓ Passed**MOT #4** 2013-09-23 13:46**MOT test number** 359086063417**Result** ✓ Passed**MOT #3** 2013-09-23 10:05**MOT test number** 386916363241**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #2** 2012-09-20 10:10**MOT test number** 699094662205**Result** ✓ Passed



MOT #1	2011-09-26 11:42
MOT test number	359479161290
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
18 October 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	18 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-29
Last registration	2023-10-19
Complete history	See info



Registration #1	2008-09-29	10 mi
Registration #2	2011-09-26	24.658 mi
Registration #3	2012-09-20	33.484 mi
Registration #4	2013-09-23	35.977 mi
Registration #5	2013-09-23	35.977 mi
Registration #6	2014-09-08	37.024 mi
Registration #7	2015-09-24	43.001 mi
Registration #8	2016-09-28	50.203 mi
Registration #9	2016-09-28	50.203 mi
Registration #10	2016-09-28	50.203 mi
Registration #11	2016-09-28	50.203 mi
Registration #12	2016-09-28	50.203 mi
Registration #13	2016-09-28	50.203 mi
Registration #14	2016-09-28	50.203 mi
Registration #15	2016-09-28	50.203 mi
Registration #16	2016-09-28	50.203 mi
Registration #17	2016-09-28	50.203 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1289 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	153102