



RENAULT

**YH60DMO**

report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO SL19 DCI 70
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

Internet history

Entry 1

Date	2021-09-28
Pictures	18
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2025-01-09
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	44
Total items failed	39

MOT #19	2024-01-10 11:56
MOT test number	183418775358
Result	✓ Passed
Next expiry date	2025-01-09
Advice	Rear Brake pipe corroded, covered in grease or other material across axle (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material inner wing (1.1.11 (c))
Advice	Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material inner wing (1.1.11 (c))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #18

2024-01-08 12:11

MOT test number

773934359150

Result

✗ Failed

- Advice

Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail

Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice

Rear Brake pipe corroded, covered in grease or other material across axle (1.1.11 (c))
- Fail

Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material inner wing (1.1.11 (c))
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail

Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail

Windscreen washer not working (3.5 (a))
- Fail

Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail

Nearside Front Direction indicator not working (4.4.1 (a) (ii))
- Advice

Nearside Front Brake pipe corroded, covered in grease or other material inner wing (1.1.11 (c))



MOT #17

2023-02-17 10:22

MOT test number

108804302358

Result

✓ Passed

- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))
- Advice

Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material Across rear axle (1.1.11 (c))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge Inner/outer edges worn (5.2.3 (e))
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material Inner wing (1.1.11 (c))



MOT #16

2023-02-15 14:58

MOT test number

324184847898

## Result

✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material Across rear axle (1.1.11 (c))
- Fail** Exhaust emissions exceed default limit of 1.5m-1 2.56m-1 (8.2.2.2 (b))
- Fail** Rear Stop lamp(s) all not working (4.3.1 (a) (iii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner/outer edges worn (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material Inner wing (1.1.11 (c))

**MOT #15**

2022-12-19 12:43

**MOT test number**

190371702853

**Result****✗ Failed**

- Fail** Offside Rear Brake pipe excessively corroded Main run chalked (1.1.11 (c))
- Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))
- Minor** Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))
- Fail** Offside Front Shock absorbers has negligible damping effect (5.3.2 (d))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Emissions not tested excessive black smoke (8.2.2.2 (e))
- Advice** Rear Brake pipe corroded, covered in grease or other material across axle brake pipe (1.1.11 (c))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both front bottom arm rear bushes worn (5.3.4 (a) (i))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))
- Fail** Nearside Front Shock absorbers has negligible damping effect (5.3.2 (d))
- Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner and outer edges (5.2.3 (e))
- Fail** Front Oil leaking excessively from engine (8.4.1 (a) (i))
- Advice** Offside Front Inner Brake pipe corroded, covered in grease or other material inner wing (1.1.11 (c))

**MOT #14**

2021-04-30 15:20

**MOT test number**

392830413566

**Result****✓ Passed**

**MOT #13** 2021-04-30 08:42**MOT test number** 301243368455**Result** ✗ Failed

- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Exhaust emissions exceed manufacturer's specified limit limit 1.3 (8.2.2.2 (a))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #12** 2020-05-13 16:04**MOT test number** 587480620644**Result** ✓ Passed**MOT #11** 2020-05-13 13:11**MOT test number** 985256045613**Result** ✗ Failed

- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Reversing lamp inoperative (4.6.1 (a))

**MOT #10** 2019-07-05 16:46**MOT test number** 448360020683**Result** ✓ Passed

- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))



**MOT #9** 2019-07-05 14:15**MOT test number** 493133171291**Result** ✗ Failed**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Exhaust emissions exceed manufacturer's specified limit limit 1.3 (8.2.2.2 (a))**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Stop lamp(s) non-obligatory stop lamp not working high level (4.3.1 (a) (ii))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #8** 2018-07-13 16:46**MOT test number** 218504351791**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2017-07-04 12:39**MOT test number** 531667056670**Result** ✓ Passed

**MOT #6** 2017-07-04 12:39**MOT test number** 520841663379**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)
- Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)
- Pass with rectification** Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**MOT #5** 2016-03-05 12:04**MOT test number** 689401300630**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2016-03-04 15:04**MOT test number** 428607985175**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2015-03-18 12:06**MOT test number** 507237475006**Result** ✓ Passed



MOT #2	2014-10-15 12:38
MOT test number	519158684230
Result	✓ Passed
MOT #1	2013-10-03 12:52
MOT test number	957746473211
Result	✓ Passed



Tax & MOT check

✗  
Untaxed

Tax expired:  
29 February 2024

✓  
MOT

Expires:  
9 January 2025

Tax status	Expired at 29 February 2024
Days left	60 days too late
MOT expiry date	9 January 2025
Full MOT history	<a href="#">See MOT history</a>



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-09-29
Last registration	2024-01-10
Complete history	<a href="#">See info</a>



Registration #1	2010-09-29	6 mi
Registration #2	2013-10-03	57.500 mi
Registration #3	2014-10-15	88.713 mi
Registration #4	2015-03-18	88.815 mi
Registration #5	2016-03-04	101.372 mi
Registration #6	2016-03-05	101.413 mi
Registration #7	2017-07-04	115.394 mi
Registration #8	2017-07-04	115.394 mi
Registration #9	2018-07-13	129.944 mi
Registration #10	2019-07-05	139.508 mi
Registration #11	2019-07-05	139.508 mi
Registration #12	2020-01-29	151.372 mi
Registration #13	2020-01-29	151.372 mi
Registration #14	2020-01-29	151.372 mi
Registration #15	2020-01-29	151.372 mi
Registration #16	2020-01-29	151.372 mi
Registration #17	2020-01-29	151.372 mi
Registration #18	2020-01-29	151.372 mi
Registration #19	2020-01-29	151.372 mi
Registration #20	2020-01-29	151.372 mi
Registration #21	2024-01-10	151.372 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2133 mm
Height	1844 mm
Length	4213 mm

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	D082219