



report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D5 POWERPULSE INSCRIPTION AWD
Colour	Grey
Year of manufacture	2018
Top speed	149 mph
0 - 60 mph	6.7 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	57.6 mpg
Consumption combined	2.8 mpg
CO2 emission	142 g/km
CO2 label	F





Internet history

Entry 4

Date	2023-03-27
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](#)

Entry 3

Date	2023-03-26
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 2

Date	2021-07-02
Pictures	35
Listing price	<a href="#">View report</a>



source: [heycar.co.uk](#)

Entry 1

Date	2021-06-04
Pictures	34
Listing price	<a href="#">View report</a>







## MOT history

MOT expiry date	2025-02-22
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	8
Total items failed	1

MOT #7	2024-02-23 17:05
MOT test number	993203295327
Result	✓ Passed
Next expiry date	2025-02-22
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6	2024-02-23 10:18
MOT test number	992926795028
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Trailer electrical socket likely to become detached (4.10 (a) (ii))

MOT #5	2023-01-27 11:23
MOT test number	981256170649
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2023-01-27 10:03**MOT test number** 151474824899**Result** ✗ Failed**MAJOR** Electronic parking brake warning indicates a malfunction (1.1.6 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2022-02-14 10:07**MOT test number** 913427894632**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2021-02-18 11:12**MOT test number** 144078147280**Result** ✓ Passed**MOT #1** 2021-02-18 11:12**MOT test number** 234931590682**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
22 February 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	22 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>First licence fee (12 months)</b>	£ 255,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 645,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2018-03-28
Last registration	2024-02-23
Complete history	<a href="#">See info</a>



Registration #1	2018-03-28	6 mi
Registration #2	2021-02-18	29.415 mi
Registration #3	2021-02-18	29.415 mi
Registration #4	2021-02-18	29.415 mi
Registration #5	2021-02-18	29.415 mi
Registration #6	2022-02-14	35.929 mi
Registration #7	2022-02-14	35.929 mi
Registration #8	2022-02-14	35.929 mi
Registration #9	2022-02-14	35.929 mi
Registration #10	2022-02-14	35.929 mi
Registration #11	2022-02-14	35.929 mi
Registration #12	2022-02-14	35.929 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1895 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1793 kg
Max. allowed weight	2360 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2605223