





report date: 2024-03-28

### General information

Make	NISSAN
Model	NV200 DCI ACENTA
Colour	White
Year of manufacture	2014
Top speed	98 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-10-17

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-11-05
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	18
Total items failed	6

MOT #13	2023-10-25 13:06
MOT test number	473282600930
Result	<b>✓</b> Passed
Next expiry date	2024-11-05

MOT #12	2023-10-25 13:06
MOT test number	774797707007
Result	<b>★</b> Failed
Pass with rectification all lamps (4.7.1 (b) (ii))	Offside Rear Registration plate lamp inoperative in the case of a single lamp or
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11		2022-10-27 14:11
MOT test	number	534483773343
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #10** 2022-10-27 08:35

**MOT test number** 669626455979

**Result** X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Nearside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Brake hydraulic reservoir fluid level below minimum level (1.1.10 (d) (i))

**MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #9 2021-11-06 08:19

**MOT test number** 381193560929

MOT #8 2021-11-04 16:45

MOT test number 765823505991

Result X Failed

**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Front Lower Suspension arm ball joint excessively worn both sides (5.3.4 (a) (i))

**DANGEROUS** Front Tyre tread depth below requirements of 1.6mm both sides (5.2.3 (e))

MOT #7 2021-06-14 13:01

**MOT test number** 191754398553

**Result** ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #6 2020-06-16 09:22

**MOT test number** 393806441422

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

MOT #5 2019-05-31 11:33

**MOT test number** 692446061628

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2018-05-01 15:05

MOT test number 132424054274

**Result** ✓ Passed

MOT #3 2018-04-30 10:21

MOT test number 311525025750

**Result** X Failed

Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)

**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)

**Fail** Offside Rear Rear position lamp(s) missing (1.1.A.3a)

**MOT #2** 2017-05-26 11:30

**MOT test number** 538297894030

**Result** ✓ Passed

**Advice** Nearside Rear Nail in tyre

**Advice** Offside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Result

Advice Offside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)

Pass with rectification Offside Front Direction indicator incorrect colour (1.4.A.2f)

Advice Nearside Rear Nail in tyre

CarCheck.co.uk page 6/13



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	5 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	history
OWITCE	Thocor y

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full re		I
***************************************		
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY		
***************************************		
	More info	>
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		
Current registration	NK WIN	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-05-07
Last registration	2023-10-25
Complete history	See info



Registration #1	2014-05-07	17 mi
Registration #2	2017-05-26	22.535 mi
Registration #3	2017-05-26	22.535 mi
Registration #4	2018-04-30	27.048 mi
Registration #5	2018-05-01	27.050 mi
Registration #6	2019-05-31	31.916 mi
Registration #7	2020-06-16	37.429 mi
Registration #8	2021-06-14	43.822 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		

More info >

CarCheck.co.uk page 12/13



BK14WOY report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	***
Adult	75%
Children	80%
Pedestrian	60%
Safety systems	38%
Overall rating	65%
Video	see crash video



# Dimensions & weight

Width	1695 mm
Height	1860 mm
Length	4400 mm
Wheel base	2725 mm
Kerb weight	1261 kg
Max. allowed weight	2000 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	2 page 13/1

Number of axles 2

**Engine number** D397398