





report date: 2024-03-29

General information

Make	CITROEN
Model	NEMO HDI 8V
Colour	Blue
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	18.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-06-03

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-08
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	17
Total items failed	4

MOT #14		2023-12-13 08:12
MOT test	number	219100582435
Result		✓ Passed
Next expi	ry date	2025-01-08
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Nearside Front Outer Seat belt anchorage prescribed area is corroded but not considered	
excessive sill (7.1.1 (a) (i))		
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)))
Advice	Advice Offside Front Outer Seat belt anchorage prescribed area is corroded but not considered excessive	
sill (7.1.1 (a) (i))		
Advice	Under body corroded	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13		2022-12-28 09:15
MOT test	number	243305675777
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



MOT #12 2021-12-23 09:08

MOT test number 360428943317

MOT #11 2021-12-23 09:08

MOT test number 771771045744

Result × Failed

Pass with rectification Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Pass with rectification Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Pass with rectification Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #10 2020-12-15 13:02

MOT test number 777089155409

Result \rightarrow Passed

Advice Rear Coil spring corroded both (5.3.1 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Power steering component has slight seepage from a component (2.1.5 (a))

MOT #9 2020-01-09 13:26

MOT test number 157245224053

MOT #8 2020-01-09 11:04

MOT test number 518115766752

Result X Failed

Fail Front Brake disc significantly and obviously worn Both front (1.1.14 (a) (i))

CarCheck.co.uk page 4/13



YS10LYR

report date: 2024-03-29

MOT #7

MOT test number

648896602847

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6 2018-05-02 10:13 **MOT test number** 641379851280 Result ✓ Passed **MOT #5** 2017-05-16 09:05 **MOT** test number 112973696435 ✓ Passed Result **MOT #4** 2016-05-19 08:21 705319358607 **MOT** test number Result ✓ Passed

 MOT #3
 2015-05-07 09:42

 MOT test number
 785437925132

 Result
 ✓ Passed

MOT test number

Result

Advice

Parking brake lever has little reserve travel (3.1.6b)

Notice

Roughness in nearside front strut top bearing

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 5/13



MOT #1 2013-06-24 10:25

MOT test number 399235673108

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	8 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

· · · · · · · · · · · · · · · · · · ·		
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		OEN
	More info	>
Plate changes See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	NK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-07-03
Last registration	2023-12-13
Complete history	See info



Registration #1	2010-07-03	20 mi
Registration #2	2013-06-24	53.245 mi
Registration #3	2014-05-21	66.045 mi
Registration #4	2015-05-07	74.611 mi
Registration #5	2016-05-19	82.010 mi
Registration #6	2017-05-16	88.310 mi
Registration #7	2018-05-02	92.427 mi
Registration #8	2019-05-17	95.843 mi
Registration #9		11.777 es
Registration #9 Registration #10		1.77 4
		11.777 ea 11.777 ea 11.777 ea
Registration #10		11.77 m
Registration #10 Registration #11		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #10 Registration #11 Registration #12		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #10 Registration #11 Registration #12 Registration #13		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	大大大 大大
Adult	59%
Children	74%
Pedestrian	55%
Safety systems	29%
Overall rating	58%
Video	see crash video



Dimensions & weight

Width	1816 mm
Height	1721 mm
Length	3959 mm
Wheel base	2513 mm
Kerb weight	1185 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FD982641028

CarCheck.co.uk page 13/13