





report date: 2024-03-29

General information

| Make | TOYOTA |
|---------------------|----------------|
| Model | RAV-4 D-4D XTR |
| Colour | Silver |
| Year of manufacture | 2009 |
| Top speed | 112 mph |
| 0 - 60 mph | 10.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 134 BHP |
|-------------------------|---------------------|
| Max. torque | 310 Nm at 2.000 rpm |
| Engine capacity | 2.231 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 34.9 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 42.8 mpg |
| CO2 emission | 173 g/km |
| CO2 label | Н |



CarCheck.co.uk page 1/15



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-04

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

MOT history

| MOT expiry date | 2025-03-17 |
|--------------------|------------|
| MOT pass rate | 62 % |
| MOT passed | 13 |
| Failed MOT tests | 8 |
| Total advice items | 33 |
| Total items failed | 14 |

| MOT #21 | | 2024-03-18 14:38 |
|--|---|------------------------|
| MOT test n | umber | 860138898100 |
| Result | | ✓ Passed |
| Next expir | y date | 2025-03-17 |
| Advice | Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) | |
| Advice (5.3.4 (a) (i) | Offside Front Suspension arm pin or bush worn but not resulting in exces | ssive movement rear |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weaken | ned (1.1.14 (a) (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Advice Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) | |
| Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i)) | | |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weak | ened (1.1.14 (a) (ii)) |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii) |) |

CarCheck.co.uk page 3/15



Fail

SP09UGN

report date: 2024-03-29

MOT #20 2024-03-18 11:24 **MOT** test number 108204257786 Result × Failed **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i)) Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Advice Minor Trailer electrical socket insecure (4.10 (a) (i)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

| MOT #19 | 2022-06-17 08:24 |
|-----------------|--|
| MOT test | number 169229776223 |
| Result | ✓ Passed |
| Advice | Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) |
| Advice | Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) |
| Advice (a) (i)) | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) |

Towbar component excessively corroded (6.1.6 (a))

| MOT #18 | 2021-06-15 12:10 |
|-----------------|------------------|
| MOT test number | 153712113996 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/15



Result

SP09UGN

report date: 2024-03-29

✓ Passed

MOT #17 2020-12-11 12:22

MOT test number 775228156746

Result
✓ Passed

MOT #16 2020-12-10 11:55

MOT test number 528999683276

Result X Failed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #15 2019-12-30 15:33

MOT test number 113921097881

Result \rightarrow Passed

MOT #14 2019-12-30 14:54

MOT test number 636945699232

Result X Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #13 2018-12-06 16:50

MOT test number 573387039540

575567655510

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #12 2018-12-06 11:28

MOT test number 645724971104

Result X Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Central Rear Seat belt buckle missing (7.1.2 (d))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2017-12-20 13:20

MOT test number 749567841825

Result \(\sqrt{Passed} \)

MOT #10 2017-12-19 11:22

MOT test number 766741348327

Result X Failed

Fail Offside rear brake binding (3.7.B.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside rear brake binding (3.7.B.1)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Front Inner Brake pad(s) less than 1.5 mm thick metal to metal (3.5.1g)

MOT #9 2016-12-29 16:52

MOT test number 123351011072

Result ✓ Passed

CarCheck.co.uk page 6/15



Advice

Result

SP09UGN

report date: 2024-03-29

✓ Passed

 MOT #8
 2016-12-29 15:04

 MOT test number
 484235457639

 Result
 X Failed

Fail Exhaust emits an excessive level of metered smoke (7.4.B.3a)

 MOT #7
 2016-12-29 09:53

 MOT test number
 277754835855

 Result
 X Failed

Fail Exhaust emits an excessive level of metered smoke (7.4.B.3a)

Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2014-12-04 11:25 **MOT** test number 479238934487 Result ✓ Passed **MOT #4** 2013-12-10 11:26 **MOT** test number 257534043355 Result ✓ Passed **MOT** #3 2012-12-19 13:05 **MOT** test number 506554652347

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT test number

Fass with rectification

Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Pass with rectification

Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

| MOT #1 | 2011-12-30 09:12 |
|-----------------|------------------|
| MOT test number | 226224461382 |
| Result | ✓ Passed |

CarCheck.co.uk page 8/15



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 33 |
| MOT expiry date | 17 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | Н |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Plate since

SP09UGN

report date: 2024-03-29

More info >

| Owner history | |
|---|-------------|
| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | |
| ********* | |
| | |
| *************************************** | |
| ********* | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| | |
| See in this check if this TOYOTA had different number plates. | |
| See in this check if this TOYOTA had different number plates. | |
| See in this check if this TOYOTA had different number plates. | UK UK |
| See in this check if this TOYOTA had different number plates. | UK UK |

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 22 |
| First mileage registration | 2009-03-01 |
| Last registration | 2024-03-18 |
| Complete history | See info |



| Registration #1 | 2009-03-01 | 8 mi |
|------------------|------------|-----------|
| Registration #2 | 2011-12-30 | 7.529 mi |
| Registration #3 | 2012-12-19 | 22.654 mi |
| Registration #4 | 2013-12-10 | 29.805 mi |
| Registration #5 | 2014-12-04 | 35.799 mi |
| Registration #6 | 2015-12-29 | 43.790 mi |
| Registration #7 | 2016-12-29 | 50.402 mi |
| Registration #8 | 2016-12-29 | 50.407 mi |
| Registration #9 | 2016-12-29 | 50.407 mi |
| Registration #10 | 2017-12-19 | 55.452 mi |
| Registration #11 | 2017-12-20 | 55.452 mi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 9.777 es |
| Registration #14 | | 71.777 es |
| Registration #15 | | 9.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 9.777 es |
| Registration #18 | | 11.777 es |
| Registration #19 | | 9.777 es |
| Registration #20 | | 11.777 es |
| Registration #21 | | 11.777 es |
| Registration #22 | | 71.777 66 |
| | | |

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1815 mm |
|---------------------|---------|
| Height | 1685 mm |
| Length | 4395 mm |
| Wheel base | 2560 mm |
| Kerb weight | 1640 kg |
| Max. allowed weight | 2190 kg |

Additional information

| Fuel tank capacity | 60 I | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 | page 15/15 |

Number of axles 2

Engine number 2AD0254354