





report date: 2024-03-28

General information

Make	HYUNDAI
Model	TUCSON GDI S BLUE DRIVE
Colour	Silver
Year of manufacture	2017
Top speed	113 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	161 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.8 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	<u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

PX67VTE report date: 2024-03-28

MOT expiry date	2025-04-13
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	13
Total items failed	2

MOT #7		2024-04-10 15:41
MOT test	number	555367163812
Result		✓ Passed
Next expiry date 2025-04		2025-04-13
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2024-04-10 11:47
MOT test number	689297533761
Result	X Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's sp (a))	pecified limits (8.2.1.2
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Exhaust emits black smoke during acceleration (8.2.1.2 (g))	

MOT #5	2023-04-12 10:16
MOT test number	927772656445
Result	✓ Passed
Advice Nearside Front Nail in tyre	

CarCheck.co.uk page 3/11



MOT #4 2022-04-07 10:42

MOT test number 485488129427

MOT #3 2022-04-06 10:41

MOT test number 792807527155

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Nail in tyre

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2021-04-14 15:10

MOT test number 709069253784

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1 2020-09-18 13:54

MOT test number 999162082954

Result

Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	13 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

Plate changes	More info >
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIV
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-10-13
Last registration	2024-04-10
Complete history	See info



Registration #1	2017-10-13	20 mi
Registration #2	2020-09-18	41.178 mi
Registration #3		11.777 es
Registration #4	2021-04-14	45.087 mi
Registration #5	2022-04-06	49.884 mi
Registration #6		0.00 44
Registration #7		11.777 mi
Registration #8		

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	71%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1645 mm
Length	4475 mm
Wheel base	2670 mm
Kerb weight	1464 kg
Max. allowed weight	1895 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number G4FDHZ947577