



YE59XFP

report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Silver
Year of manufacture	-
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg



**MOT history**

MOT #12	2021-01-18 14:16
MOT test number	709649269077
Result	✓ Passed
Next expiry date	2022-01-17
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2019-12-23 09:48
MOT test number	923191070594
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2019-12-21 08:45
MOT test number	340262406209
Result	✗ Failed
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Exhaust heat shield insecure.
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2018-12-21 09:30**MOT test number** 342599400448**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear heatshield insecure**Minor** Windscreen damaged but not adversely affecting driver's view windscreen cracked (3.2 (a) (i))**MOT #8** 2017-12-22 09:24**MOT test number** 187289422393**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2017-12-22 09:24**MOT test number** 608764536144**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Front position lamp(s) not working sidelight (1.1.A.3b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-12-15 10:40**MOT test number** 102381384176**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' windscreen slight damage (8.3.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-12-21 09:14**MOT test number** 285661094122**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-12-20 08:46**MOT test number** 349354954392**Result** ✓ Passed**MOT #3** 2013-12-23 11:03**MOT test number** 227927853366**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-01-03 14:54**MOT test number** 855833203072**Result** ✓ Passed**Advice** Offside Rear Rear fog lamp damaged, but still visible from a reasonable distance (1.3.2d)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2012-11-28 12:38**MOT test number** 649353832300**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YE59XFP
Plate since	2019-03-28
Current registration	YE59XFP
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-12-23
Last registration	2021-01-18
Complete history	See info



Registration #1	2009-12-23	22 mi
Registration #2	2012-11-28	51.420 mi
Registration #3	2013-01-03	52.542 mi
Registration #4	2013-12-23	65.221 mi
Registration #5	2014-12-20	77.387 mi
Registration #6	2015-12-21	88.487 mi
Registration #7	2016-12-15	100.668 mi
Registration #8	2017-01-01	101.000 mi
Registration #9	2017-01-01	101.000 mi
Registration #10	2017-01-01	101.000 mi
Registration #11	2017-01-01	101.000 mi
Registration #12	2017-01-01	101.000 mi
Registration #13	2017-01-01	101.000 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1257 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9D37307