





report date: 2024-03-28

General information

Make	ТОУОТА
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Silver
Year of manufacture	2004
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	130 Nm at 4.400 rpm
Engine capacity	1.398 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



MOT history

MOT expiry date	2021-05-27
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	22
Total items failed	15

MOT #22	2020-05-28 13:14
MOT test number	879318319775
Result	✓ Passed
Next expiry date	2021-05-27
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #21	2020-05-28 09:20
MOT test number	872848509032
Result	X Failed
Fail Nearside Rear Valve stem seriously damaged (5.2.3 (j))	
Fail Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))	

MOT #20		2019-05-28 09:29
MOT test	number	808799421697
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice (c))	Brake pipe corroded, covered in grease or other material 2 x front to rear [r	rear sections] (1.1.11

CarCheck.co.uk page 2/13



AK04FLC

report date: 2024-03-28

MOT #19 2018-05-16 09:20

MOT test number 208517507359

Result ✓ Passed

MOT #18 2017-05-26 13:22

MOT test number 134610834590

Result
✓ Passed

MOT #17 2017-05-26 09:38

MOT test number 623534066926

Result X Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Front brake application uneven (3.7.B.2)

Fail Front brake binding (3.7.B.1)

MOT #16 2016-05-26 06:39

MOT test number 406163066945

Result
✓ Passed

MOT #15 2016-05-25 08:55

MOT test number 916195265471

Result ★ Failed

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Fail Exhaust has a major leak of exhaust gases (7.1.2)

MOT #14 2015-05-29 14:13

MOT test number 188059145133

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 3/13



MOT #13 2015-03-23 09:13

MOT test number 875772585079

Result ✓ Passed

Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Nearside Rear coil spring corroded (2.4.C.1b)

MOT #12 2014-04-03 11:27

MOT test number 739993594080

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Rear coil spring corroded (2.4.C.1b)

MOT #11 2014-04-03 08:16

MOT test number 955253894028

Result × Failed

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Advice Offside Rear coil spring corroded (2.4.C.1b)

MOT #10 2013-04-08 10:21

MOT test number 448658393017

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 4/13



MOT #9 2013-04-08 10:21

MOT test number 848718993041

Result X Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #8 2012-04-12 11:58

MOT test number 895903502140

Result

Passed

Notice Both rear tyres cracking on sidewalls

MOT #7 2011-04-05 10:00

MOT test number 135495891063

Result \rightarrow Passed

Advice Parking brake lever has little reserve travel (3.1.6b)

MOT #6 2010-03-24 16:51

MOT test number 812223080008

MOT #5 2010-03-24 12:51

MOT test number 923323280026

Result X Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #4 2009-04-03 09:36

MOT test number 751653399099

Result
✓ Passed

CarCheck.co.uk page 5/13



Result

Fail

AK04FLC

report date: 2024-03-28

X Failed

MOT #3 2008-04-09 12:28

MOT test number 820620408187

Result \rightarrow Passed

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2008-04-09 09:29

MOT test number 483800708121

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

0.13.43 .164. 514.16 4.155 .161.17 p.1164 6. 565.164.7 sat 1.615.61.7 meanoning (5.15.12.7)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #1 2007-04-12 10:04

MOT test number 312162907171

Result
✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



Tax & MOT check



MOT

Expired:
27 May 2021

Tax expired: 13 January 2021

Tax status

Days left

1201 days too late

MOT expiry date

Full MOT history

Expired at 13 January 2021

1201 days too late

27 May 2021

See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full is)TA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		7
Current registration	UK UK	
Plate since		
Current registration	OK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-04-15
Last registration	2020-05-28
Complete history	See info



2004-04-15	24 mi
2007-04-12	18.064 mi
2008-04-09	24.369 mi
2008-04-09	24.369 mi
2009-04-03	29.685 mi
2010-03-24	32.973 mi
2010-03-24	32.973 mi
2011-04-05	37.458 mi
2012-04-12	42.304 mi
2013-04-08	45.003 mi
2014-04-03	47.057 mi
	11.777 es
	91.777 esi
	11.777 es
	91.777 esi
	11.777 es
	9.777 es
	11.777 es
	9.777 es
	11.777 es
	11,177 es
	2007-04-12 2008-04-09 2009-04-03 2010-03-24 2010-03-24 2011-04-05 2012-04-12 2013-04-08 2014-04-03

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1130 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	4ZZU499329

CarCheck.co.uk page 13/13