



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT3
Colour	Silver
Year of manufacture	2003
Top speed	106 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-05
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-27
MOT pass rate	89 %
MOT passed	17
Failed MOT tests	2
Total advice items	26
Total items failed	1

MOT #19	2023-06-28 10:40
MOT test number	439511900170
Result	✓ Passed
Next expiry date	2024-06-27
Advice	Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
Advice	Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Advice	Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))

MOT #18	2022-04-25 15:32
MOT test number	381986327298
Result	✓ Passed

MOT #17	2022-04-25 15:32
MOT test number	613152556633
Result	✗ Failed
Pass with rectification	Nearside Front Suspension arm likely to become detached wishbone bush loose (5.3.3 (a) (ii))

**MOT #16**

2021-04-24 08:39

MOT test number

510625467833

Result

✓ Passed

Advice

Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #15

2020-07-09 08:14

MOT test number

123702013845

Result

✓ Passed

Advice

Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge - very almost too excess (5.2.3 (e))

Minor

Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Minor

Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Exhaust has a minor leak of exhaust gases rear silencer (6.1.2 (a))

Minor

Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Minor

Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14

2019-04-17 12:13

MOT test number

361707197700

Result

✓ Passed

Minor

Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor

Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened lipped and worn (1.1.14 (a) (ii))

**MOT #13** 2019-04-17 08:46**MOT test number** 175324523785**Result** ✗ Failed**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**MAJOR** Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened lipped and worn (1.1.14 (a) (ii))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MAJOR** Front Service brake excessively binding both (1.2.1 (f))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #12** 2018-04-20 13:14**MOT test number** 728015849015**Result** ✓ Passed**MOT #11** 2017-04-20 09:48**MOT test number** 406227936016**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2016-04-14 11:55**MOT test number** 528473353897**Result** ✓ Passed**MOT #9** 2015-04-08 08:55**MOT test number** 366988895040**Result** ✓ Passed

**MOT #8** 2014-04-14 16:23**MOT test number** 268454704479**Result** ✓ Passed**MOT #7** 2013-04-16 14:08**MOT test number** 827436903147**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-04-16 09:34**MOT test number** 117497802120**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-04-18 13:11**MOT test number** 519338701160**Result** ✓ Passed**MOT #4** 2010-04-21 15:03**MOT test number** 590401410125**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2009-01-20 13:57**MOT test number** 513210529011**Result** ✓ Passed



MOT #2	2008-01-21 08:37
MOT test number	434321028029
Result	✓ Passed

MOT #1	2006-12-28 12:00
MOT test number	831002766399
Result	✓ Passed




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-11-03
Last registration	2023-06-28
Complete history	See info



Registration #1	2003-11-03	13 mi
Registration #2	2006-12-28	20.678 mi
Registration #3	2008-01-21	25.103 mi
Registration #4	2009-01-20	29.514 mi
Registration #5	2010-04-21	35.530 mi
Registration #6	2011-04-18	40.237 mi
Registration #7	2012-04-16	44.660 mi
Registration #8	2013-04-16	47.701 mi
Registration #9	2014-04-14	50.972 mi
Registration #10	2015-04-08	54.262 mi
Registration #11	2016-04-14	57.939 mi
Registration #12	2017-04-14	61.616 mi
Registration #13	2018-04-14	65.293 mi
Registration #14	2019-04-14	68.970 mi
Registration #15	2020-04-14	72.647 mi
Registration #16	2021-04-14	76.324 mi
Registration #17	2022-04-14	80.001 mi
Registration #18	2023-04-14	83.678 mi
Registration #19	2024-04-14	87.355 mi
Registration #20	2025-04-14	91.032 mi
Registration #21	2026-04-14	94.709 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1705 mm
Length	4265 mm
Wheel base	2490 mm
Kerb weight	1490 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	1CD0338466