



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Black
Year of manufacture	2008
Top speed	132 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.8 mpg
CO2 emission	176 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-17
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-28
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	43
Total items failed	4

MOT #16	2023-10-20 10:16
---------	------------------

MOT test number	282054960635
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-28
------------------	------------

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner very close to cords showing (5.2.3 (e))
- Minor** Rear Position lamp has a product on the lens or light source which obviously reduces light intensity (4.2.3 (b) (i))
- Advice** Offside rear light unit cracked lens
- Advice** Rear Sub-frame corroded but not seriously weakened Plus rear suspension couplings heavily corroded (5.3.3 (b) (i))
- Advice** Exhaust system and exhaust hanger heavily corroded
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Parking brake lever close to reserve travel
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Vehicle under carriage heavily corroded

**MOT #15** 2022-10-25 12:00**MOT test number** 894806882539**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #14** 2021-10-12 16:03**MOT test number** 702342201319**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2020-10-29 10:11**MOT test number** 573461246057**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #12** 2020-10-29 10:11**MOT test number** 716942648784**Result** ✗ Failed

- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Horn not working (7.7 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #11 2019-10-28 12:01**MOT test number** 414041840822**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10 2018-10-27 08:43**MOT test number** 850870528603**Result** ✓ Passed**MOT #9** 2017-10-10 09:15**MOT test number** 229277523012**Result** ✓ Passed

**MOT #8** 2016-10-11 14:19**MOT test number** 271296611883**Result** ✓ Passed

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7 2016-10-06 11:23**MOT test number** 146370486847**Result** ✗ Failed

Fail Offside Rear Suspension arm rubber bush bonding deteriorated resulting in excessive movement trailing arm front bush (2.4.G.2)

Advice Passenger seat(s) missing at time of test both rear seats folded

Advice Low emitter no emissions print out available

Fail Nearside Rear Suspension arm rubber bush deteriorated resulting in excessive movement trailing arm front bush (2.4.G.2)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #6 2015-10-09 11:13**MOT test number** 509463162321**Result** ✓ Passed**MOT #5** 2014-10-28 16:34**MOT test number** 956611304322**Result** ✓ Passed

Notice Centre brake light not working

Notice Non obligatory mirror damaged

Advice Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2014-10-28 12:05**MOT test number** 757081104366**Result** ✗ Failed**Notice** Centre brake light not working**Fail** Horn not working (1.6.2a)**Notice** Non obligatory mirror damaged**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2013-10-25 13:01**MOT test number** 578958693235**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2012-10-12 12:22**MOT test number** 818326882206**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-10-12 14:48**MOT test number** 299515581207**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
28 October 2024

Tax status		Valid until 1 November
Days left		185
MOT expiry date		28 October 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2023-03-28
Current registration	 XXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-10-24
Last registration	2023-10-20
Complete history	See info



Registration #1	2008-10-24	22 mi
Registration #2	2011-10-12	27.917 mi
Registration #3	2012-10-12	37.681 mi
Registration #4	2013-10-25	49.090 mi
Registration #5	2014-10-28	59.786 mi
Registration #6	2014-10-28	59.786 mi
Registration #7	2015-10-09	67.433 mi
Registration #8	2016-10-06	77.456 mi
Registration #9	2016-10-11	77.561 mi
Registration #10	2016-10-11	77.561 mi
Registration #11	2016-10-11	77.561 mi
Registration #12	2016-10-11	77.561 mi
Registration #13	2016-10-11	77.561 mi
Registration #14	2016-10-11	77.561 mi
Registration #15	2016-10-11	77.561 mi
Registration #16	2016-10-11	77.561 mi
Registration #17	2016-10-11	77.561 mi
Registration #18	2016-10-11	77.561 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1974 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

8K76718