



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Grey
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-10-31
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-10-28
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	10
Total items failed	11

MOT #13	2021-10-27 13:36
MOT test number	786949982653
Result	✓ Passed
Next expiry date	2022-10-28

MOT #12	2021-10-25 16:36
MOT test number	212734096163
Result	✗ Failed
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

MOT #11	2020-10-29 09:04
MOT test number	443075638536
Result	✓ Passed
Advice	Undertray not fully secure (8.1.1 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #10** 2020-10-28 17:04**MOT test number** 299544663024**Result** ✗ Failed

- Advice** Undertray not fully secure (8.1.1 (b) (i))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #9 2019-10-10 15:26**MOT test number** 115662626254**Result** ✓ Passed

- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Offside rear brake squeaking

MOT #8 2019-10-10 12:10**MOT test number** 629008177127**Result** ✗ Failed

- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside rear brake squeaking

MOT #7 2018-10-12 15:23**MOT test number** 629772283994**Result** ✓ Passed

**MOT #6** 2018-10-11 13:38**MOT test number** 671621408456**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #5** 2017-08-11 14:59**MOT test number** 400558041524**Result** ✓ Passed**MOT #4** 2017-08-11 10:28**MOT test number** 346444521436**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #3** 2016-08-05 11:00**MOT test number** 569702238150**Result** ✓ Passed**MOT #2** 2015-08-11 11:18**MOT test number** 335996586945**Result** ✓ Passed**MOT #1** 2014-07-15 11:55**MOT test number** 279166394104**Result** ✓ Passed



Tax & MOT check

×

Untaxed

Tax expired:
1 November 2021

×

MOT

Expired:
28 October 2022

Tax status	Expired at 1 November 2021
Days left	911 days too late
MOT expiry date	28 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LT11UBY
Plate since	2024-03-28
Current registration	 LT11UBY
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-05-28
Last registration	2021-10-27
Complete history	See info



Registration #1	2011-05-28	6 mi
Registration #2	2014-07-15	14.261 mi
Registration #3	2015-08-11	25.731 mi
Registration #4	2016-08-05	34.560 mi
Registration #5	2017-08-11	43.176 mi
Registration #6	2017-08-11	43.177 mi
Registration #7	2018-10-11	50.560 mi
Registration #8	2018-10-12	50.560 mi
Registration #9	2019-05-29	55.277 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi
Registration #15	2019-05-29	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

CAY 586764