



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 T5 SE V50
Colour	Red
Year of manufacture	2004
Top speed	149 mph
0 - 60 mph	6.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	220 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	32.1 mpg
CO2 emission	209 g/km
CO2 label	K





MOT history

MOT expiry date	2020-11-14
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	9
Total items failed	15

MOT #19	2019-05-15 09:12
MOT test number	811815111957
Result	✓ Passed
Next expiry date	2020-11-14

MOT #18	2019-05-15 09:12
MOT test number	215200997793
Result	✗ Failed
Pass with rectification	Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

MOT #17	2018-04-27 11:12
MOT test number	907808275024
Result	✓ Passed
Advice	Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)

MOT #16	2017-05-05 11:22
MOT test number	762696139508
Result	✓ Passed
Advice	Nearside Front Inner Tyre worn close to the legal limit side (4.1.E.1)
Advice	Offside Front Inner Tyre worn close to the legal limit side (4.1.E.1)

**MOT #15**

2017-04-18 13:03

MOT test number

570553932683

Result**✗ Failed**

Fail Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Nearside Front Front suspension has excessive play in a track control arm inner bush (2.5.B.2b)

Fail Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

Fail Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Front Front suspension has excessive play in a track control arm inner bush (2.5.B.2b)

MOT #14

2016-04-18 14:20

MOT test number

412414867401

Result**✓ Passed**

Advice Nearside Front Front suspension has slight play in a track control arm inner bush rear (2.5.B.2b)

MOT #13

2016-04-18 10:15

MOT test number

644689143067

Result**✗ Failed**

Fail Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

MOT #12

2015-06-03 13:40

MOT test number

445894655198

Result**✓ Passed****MOT #11**

2014-09-30 16:01

MOT test number

317873574247

Result**✓ Passed**

**MOT #10** 2014-09-26 16:46**MOT test number** 626869864212**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**Advice** Rear Parking brake lever has little reserve travel (3.1.6b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #9** 2013-08-29 13:26**MOT test number** 999441943299**Result** ✓ Passed**MOT #8** 2012-08-01 17:34**MOT test number** 809134312250**Result** ✓ Passed**Notice** Engine management light on dash**MOT #7** 2012-08-01 10:10**MOT test number** 837034012291**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Engine management light on dash**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #6** 2011-08-01 13:59**MOT test number** 106833611227**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2010-08-05 10:08**MOT test number** 374477210261**Result** ✓ Passed**MOT #4** 2009-10-28 11:23**MOT test number** 330331309386**Result** ✓ Passed**MOT #3** 2009-10-28 11:23**MOT test number** 251471309369**Result** ✗ Failed**Pass with rectification** Offside Outer Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #2** 2008-10-10 13:37**MOT test number** 530104288221**Result** ✓ Passed**MOT #1** 2007-10-05 16:25**MOT test number** 733128277282**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
16 November 2020

✕
MOT

Expired:
14 November 2020

Tax status	Expired at 16 November 2020
Days left	1259 days too late
MOT expiry date	14 November 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	ND54SYX
Plate since	2024-03-28
Current registration	ND54SYX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-10-29
Last registration	2019-05-15
Complete history	See info



Registration #1	2004-10-29	22 mi
Registration #2	2007-10-05	33.785 mi
Registration #3	2008-10-10	46.847 mi
Registration #4	2009-10-28	58.699 mi
Registration #5	2010-08-05	63.849 mi
Registration #6	2011-08-01	76.410 mi
Registration #7	2012-08-01	88.162 mi
Registration #8	2012-08-01	88.162 mi
Registration #9	2013-08-29	97.680 mi
Registration #10	2014-09-26	109.433 mi
Registration #11	2015-05-20	121.277 mi
Registration #12	2016-05-20	133.121 mi
Registration #13	2017-05-20	144.965 mi
Registration #14	2018-05-20	156.809 mi
Registration #15	2019-05-15	168.653 mi
Registration #16	2019-05-15	168.653 mi
Registration #17	2019-05-15	168.653 mi
Registration #18	2019-05-15	168.653 mi
Registration #19	2019-05-15	168.653 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1451 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	3548650