





General information

| Make | VOLVO |
|---------------------|----------------------|
| Model | V40 T3 CROSS COUNTRY |
| Colour | Red |
| Year of manufacture | 2017 |
| Top speed | 130 mph |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 150 BHP | 0 < 101 A |
|-------------------------|---------------------|-------------|
| Max. torque | 250 Nm at 1.700 rpm | 101 - 120 B |
| Engine capacity | 1.498 cc | 121 - 140 E |
| Cylinders | 4 | 141 - 165 F |
| Fuel type | Petrol | 166 - 185 H |
| Consumption city | 38.2 mpg | 186 - 225 J |
| Consumption extra urban | 61.4 mpg | 225+ |
| Consumption combined | 50.4 mpg | |
| CO2 emission | 131 g/km | |
| CO2 label | E | |





Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-02-06 |
| Pictures | 10 |
| Listing price | View report |
| | |







source: autoonline.co.uk



MOT history

| MOT expiry date | 2023-01-07 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 3 |
| Total items failed | 0 |

| MOT #3 | | 2022-01-08 17:46 |
|-----------|--|------------------|
| MOT test | number | 225732845659 |
| Result | | Passed |
| Next expi | ry date | 2023-01-07 |
| Advice | Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #2 | 2020-11-09 13:17 |
|-----------------|------------------|
| MOT test number | 896441636852 |
| Result | ✓ Passed |
| | |

| MOT #1 | 2020-07-23 10:14 |
|-----------------------------------|------------------|
| MOT test number | 482452846214 |
| Result | ✓ Passed |
| Advice COVID-19 6 MONTH EXTENSION | |



Tax & MOT check

| X Untaxed Tax expired: 8 October 2022 | X MOT Expired: 7 January 2023 |
|--|--|
| Tax status | Expired at 8 October 2022 |
| Days left | 569 days too late |
| MOT expiry date | 7 January 2023 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | FE CO |
| Category | Lashe |
| Туре | |
| Damage 2 | AMPLE |
| Damaye 2 | e e et al |
| Date | 1. |
| Category | AMP |
| Туре | |

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ********* | |
| ******** | |
| ****** | |
| ********* | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | |





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles | \uparrow |
|----------------------------|------------|--------------------------|
| Mileage registrations | 4 | |
| First mileage registration | 2017-07-31 | Ē |
| Last registration | 2022-01-08 | |
| Complete history | See info | |
| | | |
| | | vehicle age $ ightarrow$ |

| Registration #1 | 2017-07-31 | 26 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-11-09 | 14.796 mi |
| Registration #3 | | 11.777 esi |
| Registration #4 | | 11.777 esi |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| S0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 98% |
| Children | 75% |
| Pedestrian | 88% |
| Safety systems | 100% |
| Overall rating | 92% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1857 mm |
| Height | 1470 mm |
| Length | 4370 mm |
| Wheel base | 2646 mm |
| Kerb weight | 1432 kg |
| Max. allowed weight | 1975 kg |
| Additional information | |
| Fuel tank capacity | 62 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 10/10 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | 2157273 |