





report date: 2024-03-28

General information

Make	MINI
Model	COOPER SD COOPER
Colour	Red
Year of manufacture	2012
Top speed	119 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12





Internet history

Entry 3

Date 2023-04-29

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 2

Date 2023-04-04

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

Entry 1

Date 2021-07-22

Pictures

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-10
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #11	2023-09-11 14:35
MOT test number	842077814458
Result	✓ Passed
Next expiry date	2024-09-10

MOT #10	2022-05-16 08:50
MOT test number	783420206619
Result	✓ Passed

MOT #9	2021-05-26 09:44
MOT test	number 263890968823
Result	✓ Passed
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #8		2020-06-01 13:54
MOT test	number	980649664590
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



Result

Pass with rectification

WV12HXT report date: 2024-03-28

× Failed

MOT #7 2019-05-22 15:40

MOT test number 438288501852

Result ✓ Passed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2018-05-25 07:43

MOT test number 583211243294

Result ✓ Passed

MOT #5 2018-05-25 07:43

MOT test number 378348414437

MOT #4 2017-05-15 10:04

Nearside Front Position lamp not working (4.2.1 (a))

MOT test number 809344334262

Result
✓ Passed

MOT #3 2016-04-30 08:59

MOT test number 601051360264

Result

Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2015-05-15 15:19

MOT test number 319245335180

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #1 2015-02-12 09:16

MOT test number 429063745026

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



✓ MOT

Expires: 10 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	10 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report h		e?
THE STATE OF THE S		

	More info	>
Plate changes See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-01
Last registration	2023-09-11
Complete history	See info



Registration #1	2012-03-01	7 mi
Registration #2	2015-02-12	27.229 mi
Registration #3	2015-05-15	28.273 mi
Registration #4	2016-04-30	36.151 mi
Registration #5	2017-05-15	40.112 mi
Registration #6	2018-05-25	45.887 mi
Registration #7	2018-05-25	45.887 mi
Registration #8	2019-05-22	51.207 mi
Registration #9		11.777 es
Registration #10		77,777 46
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		71.777 66
Registration #14		0.00 44
Registration #15		11.777 ms

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1205 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/12