



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | JAGUAR         |
| Model               | X-TYPE SE      |
| Colour              | Blue           |
| Year of manufacture | 2005           |
| Top speed           | 137 mph        |
| 0 - 60 mph          | 8.5 seconds    |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 152 BHP             |
| Max. torque             | 366 Nm at 1.800 rpm |
| Engine capacity         | 2.198 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 34.0 mpg            |
| Consumption extra urban | 60.1 mpg            |
| Consumption combined    | 47.1 mpg            |
| CO2 emission            | 159 g/km            |
| CO2 label               | G                   |






Internet history

Entry 3

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-07-23                  |
| Pictures      | 9                           |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](#)

Entry 2

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-07-14                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: [cargurus.co.uk](#)

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-07-13                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: [autotrader.co.uk](#)



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-01-19 |
| MOT pass rate      | 70 %       |
| MOT passed         | 16         |
| Failed MOT tests   | 7          |
| Total advice items | 56         |
| Total items failed | 12         |

MOT #232024-01-15 14:24

MOT test number669763681194

Result✓ Passed

Next expiry date2025-01-19

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Nail in tyre
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both worn at inner face (1.1.14 (a) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))
- Advice** Central Exhaust heat shield insecure
- Advice** Fuel Pipe/s corroded
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing both cracked at tread (5.2.3 (d) (ii))
- Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #22**

2024-01-15 11:25

**MOT test number**

465922924054

**Result**

✗ Failed

- Advice** Central Exhaust heat shield insecure
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both worn at inner face (1.1.14 (a) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Offside Rear Nail in tyre
- Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing both cracked at tread (5.2.3 (d) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Fuel Pipe/s corroded
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))

**MOT #21**

2023-01-19 11:39

**MOT test number**

358410949663

**Result**

✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material n/s and o/s corroded (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s corrosion on inner faces (1.1.14 (a) (ii))
- Advice** Nearside Front Brake hose slightly deteriorated not mounted to midway fixing (resecured ) (1.1.12 (b) (ii))

**MOT #20** 2022-01-14 14:28**MOT test number** 772853869809**Result** ✓ Passed**MOT #19** 2022-01-11 10:38**MOT test number** 253414537510**Result** ✗ Failed

**Fail** Nearside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced OUTER SILL CORROSION. (6.1.1 (c) (i))

**Advice** Nearside Rear Nail in tyre

**Fail** Offside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced OUTER SILL CORROSION. (6.1.1 (c) (i))

**MOT #18** 2021-10-05 09:19**MOT test number** 743621917495**Result** ✗ Failed

**Advice** Rear Shock absorbers has light misting of oil Both (5.3.2 (b))

**Fail** Front Tyre tread depth below requirements of 1.6mm Both (5.2.3 (e))

**Minor** Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Fail** Windscreen in an unacceptable condition (3.2 (c) (i))

**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Both sill covered at the time test

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17** 2021-01-20 14:56**MOT test number** 501559013652**Result** ✓ Passed

**MOT #16** 2020-01-14 15:43**MOT test number** 397395763565**Result** ✓ Passed**MOT #15** 2020-01-09 12:04**MOT test number** 844071930974**Result** ✗ Failed**Fail** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #14** 2018-12-14 12:24**MOT test number** 881646857087**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2018-12-14 09:53**MOT test number** 158211591665**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2017-12-05 13:45**MOT test number** 101260509448**Result** ✓ Passed**Advice** OSR BRAKE CALIPER DAMP, HANDBRAKE ARM APPEARS TO BE GREASED

**MOT #11** 2017-12-05 13:45**MOT test number** 853377964992**Result** ✗ Failed

**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' SAT NAV (8.3.1e)

**Advice** OSR BRAKE CALIPER DAMP, HANDBRAKE ARM APPEARS TO BE GREASED

**MOT #10** 2016-12-08 12:49**MOT test number** 462052418406**Result** ✓ Passed

**Advice** Offside Front washer out of the two jets only on working

**Advice** Nearside Front washer out of the two jets only on working

**Advice** Nearside Rear Nail in tyre

**MOT #9** 2015-12-10 09:10**MOT test number** 649773401591**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2015-12-09 16:49**MOT test number** 124139783390**Result** ✗ Failed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-12-03 15:13**MOT test number** 466137534443**Result** ✓ Passed**MOT #6** 2013-12-17 11:32**MOT test number** 556631853332**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2012-12-17 11:28**MOT test number** 407422152319**Result** ✓ Passed**Notice** Tow ball/hitch not fitted at time of test**MOT #4** 2011-12-09 10:29**MOT test number** 378823141377**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)





|                 |                  |
|-----------------|------------------|
| MOT #3          | 2010-12-10 10:40 |
| MOT test number | 933244240373     |
| Result          | ✓ Passed         |

|  |                  |
|--|------------------|
| MOT #2   | 2009-12-11 11:38 |
| MOT test number  | 543505049386     |
| Result   | ✓ Passed         |
| <div>Advice</div> Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |                  |

|                 |                  |
|-----------------|------------------|
| MOT #1          | 2008-12-12 09:12 |
| MOT test number | 444327448475     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
19 January 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 October           |
| <b>Days left</b>        | 155                             |
| <b>MOT expiry date</b>  | 19 January 2025                 |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | G          |
| <b>Single payment (12 months)</b>              | £ 240,00,- |
| <b>Single six month payment</b>                | £ 132,00,- |
| <b>Total payable by 12 monthly instalments</b> | £ 252,00,- |



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,200 |
| Auction value               | £ 19,200 |
| Average private trade value | £ 19,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |            |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>RL55NSK</b> |
| Plate since          | 2024-03-28   |
| Current registration |  <b>RL55NSK</b> |
| Plate since          | 2024-03-28   |

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

|                   |                 |
|-------------------|-----------------|
| Finance company   | XXXXXXXXXX XXXX |
| Date of agreement | XXXXXXXXXX XXXX |
| Agreement type    | XXXXXXXXXX XXXX |
| Agreement term    | XXXXXXXXXX XXXX |
| Agreement number  | XXXXXXXXXX XXXX |
| Contact info      | XXXXXXXXXX XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 27                       |
| First mileage registration | 2005-12-28               |
| Last registration          | 2024-01-15               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2005-12-28 | 23 mi      |
| Registration #2  | 2008-12-12 | 17.466 mi  |
| Registration #3  | 2009-12-11 | 22.558 mi  |
| Registration #4  | 2010-12-10 | 26.653 mi  |
| Registration #5  | 2011-12-09 | 32.012 mi  |
| Registration #6  | 2012-12-17 | 35.646 mi  |
| Registration #7  | 2013-12-17 | 39.328 mi  |
| Registration #8  | 2014-12-03 | 47.082 mi  |
| Registration #9  | 2015-12-09 | 56.049 mi  |
| Registration #10 | 2015-12-10 | 56.049 mi  |
| Registration #11 | 2016-12-08 | 64.092 mi  |
| Registration #12 | 2017-12-05 | 78.514 mi  |
| Registration #13 | 2017-12-05 | 78.514 mi  |
| Registration #14 | 2018-12-14 | 94.144 mi  |
| Registration #15 | 2019-01-29 | 101.277 mi |
| Registration #16 | 2019-01-29 | 101.277 mi |
| Registration #17 | 2019-01-29 | 101.277 mi |
| Registration #18 | 2019-01-29 | 101.277 mi |
| Registration #19 | 2019-01-29 | 101.277 mi |
| Registration #20 | 2019-01-29 | 101.277 mi |
| Registration #21 | 2019-01-29 | 101.277 mi |
| Registration #22 | 2019-01-29 | 101.277 mi |
| Registration #23 | 2019-01-29 | 101.277 mi |
| Registration #24 | 2019-01-29 | 101.277 mi |
| Registration #25 | 2019-01-29 | 101.277 mi |
| Registration #26 | 2019-01-29 | 101.277 mi |

More info >





Safety ratings

|             |                                 |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆                           |
| Video       | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2003 mm |
| Height              | 1392 mm |
| Length              | 4672 mm |
| Wheel base          | 2710 mm |
| Kerb weight         | 1502 kg |
| Max. allowed weight | 2035 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 61 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 4                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | 050817045126BG   |