



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D3 ES
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 2

Date	2022-02-17
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 1

Date	2022-02-16
Pictures	23
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-12-03
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	22
Total items failed	3

## MOT #12 2023-11-27 14:24

MOT test number 814822036187

Result ✓ Passed

Next expiry date 2024-12-03

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

## MOT #11 2022-11-22 17:23

MOT test number 582942261746

Result ✓ Passed

**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10**

2021-11-22 09:37

**MOT test number**

145216045150

**Result**

✓ Passed

**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #9**

2020-11-24 08:08

**MOT test number**

518936795274

**Result**

✓ Passed

**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #8**

2019-11-14 17:15

**MOT test number**

776344326233

**Result**

✓ Passed

**MOT #7**

2019-11-13 09:14

**MOT test number**

189034301122

**Result**

✗ Failed

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #6** 2018-12-01 11:52**MOT test number** 986758882962**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Both rear tyres wearing on inner edge**MOT #5** 2017-12-04 11:51**MOT test number** 670304839103**Result** ✓ Passed**MOT #4** 2017-01-31 09:43**MOT test number** 314363263258**Result** ✓ Passed**Advice** Tyre worn close to the legal limit Both front on edges 205/50/17 V (4.1.E.1)**MOT #3** 2016-01-13 10:39**MOT test number** 138353181164**Result** ✓ Passed**MOT #2** 2015-01-28 14:16**MOT test number** 655888425054**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-01-29 12:32**MOT test number** 696599124003**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
3 December 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	3 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>WN60FVO</b>
Plate since	2019-09-29
Current registration	<b>WN60FVO</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-01-26
Last registration	2023-11-27
Complete history	<a href="#">See info</a>



Registration #1	2011-01-26	15 mi
Registration #2	2014-01-29	27.681 mi
Registration #3	2015-01-28	37.048 mi
Registration #4	2016-01-13	45.427 mi
Registration #5	2017-01-31	55.253 mi
Registration #6	2017-12-04	64.063 mi
Registration #7	2018-12-01	73.759 mi
Registration #8	2019-11-13	81.271 mi
Registration #9	2020-05-20	90.000 mi
Registration #10	2021-05-20	90.000 mi
Registration #11	2022-05-20	90.000 mi
Registration #12	2023-05-20	90.000 mi
Registration #13	2024-05-20	90.000 mi
Registration #14	2025-05-20	90.000 mi
Registration #15	2026-05-20	90.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1504 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1012435