



**KW56BFO**

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Red
Year of manufacture	-
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg






Internet history

Entry 1

Date	2021-08-13
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #18** 2022-12-14 11:21**MOT test number** 678325064698**Result** ✓ Passed**Next expiry date** 2023-12-30**Advice** Rear Coil spring corroded nearside and offside (5.3.1 (b) (i))**Advice** Tyre worn close to legal limit/worn on edge all four tyres scrubbed inner edges (5.2.3 (e))**Advice** Rear boot floor corroded**Minor** Front Headlamp lens slightly defective nearside and offside (4.1.1 (b) (i))**Advice** Offside Rear shockabsorber dirt cover detached**MOT #17** 2022-12-14 10:21**MOT test number** 359639592896**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Rear Exhaust has a major leak of exhaust gases silencer missing (6.1.2 (a))**Minor** Front Headlamp lens slightly defective nearside and offside (4.1.1 (b) (i))**Advice** Rear boot floor corroded**Advice** Rear Coil spring corroded nearside and offside (5.3.1 (b) (i))**Advice** Tyre worn close to legal limit/worn on edge all four tyres scrubbed inner edges (5.2.3 (e))**Fail** Front Windscreen wiper not working nearside and offside (3.4 (a))**Advice** Offside Rear shockabsorber dirt cover detached**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt also freeplay (5.3.4 (b) (ii))

**MOT #16** 2021-12-31 14:58**MOT test number** 816184347949**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**MOT #15** 2020-12-01 09:24**MOT test number** 664170208626**Result** ✓ Passed**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #14** 2019-12-16 12:31**MOT test number** 109041121706**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Slight Perishing to Both Rear Tyre's**Advice** Both Front Tyre's Wearing Edges

**MOT #13** 2019-12-16 09:25**MOT test number** 611708937190**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage missing (5.3.3 (a) (ii))**Advice** Slight Perishing to Both Rear Tyre's**Fail** Nearside Front Anti-roll bar linkage missing (5.3.3 (a) (ii))**Advice** Both Front Tyre's Wearing Edges**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #12** 2018-12-03 13:17**MOT test number** 969158020165**Result** ✓ Passed**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #11** 2017-12-18 15:16**MOT test number** 516606418034**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #10** 2016-12-28 13:37**MOT test number** 827550682302**Result** ✓ Passed**Advice** Underbody covers fitted**Advice** Parking brake lever has little reserve travel slightly long (3.1.6b)**MOT #9** 2016-12-28 09:11**MOT test number** 218104715861**Result** ✗ Failed**Advice** Parking brake lever has little reserve travel slightly long (3.1.6b)**Advice** Underbody covers fitted**Fail** Registration plate lamp not working both rear (1.1.C.1d)**Fail** Nearside Front Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #8** 2015-12-03 15:59**MOT test number** 773209437295**Result** ✓ Passed**MOT #7** 2015-01-22 15:07**MOT test number** 187862525068**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)

**MOT #6** 2015-01-15 09:51**MOT test number** 109865715484**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Rear rear brake binding (3.7.B.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Near side front tyre worn on outer edge.**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**MOT #5** 2014-01-15 09:46**MOT test number** 137575114422**Result** ✓ Passed**Advice** Offside Front Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #4** 2012-12-24 09:37**MOT test number** 598429952320**Result** ✓ Passed**MOT #3** 2011-12-20 12:48**MOT test number** 457284951467**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2010-12-24 09:36
MOT test number	830808750362
Result	✓ Passed
MOT #1	2009-12-10 10:22
MOT test number	622834849394
Result	✓ Passed





## Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

### Damage 1

Date	
Category	
Type	

### Damage 2

Date	
Category	
Type	



### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

[More info](#) >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-12-29
Last registration	2022-12-14
Complete history	<a href="#">See info</a>



Registration #1	2006-12-29	23 mi
Registration #2	2009-12-10	20.537 mi
Registration #3	2010-12-24	25.175 mi
Registration #4	2011-12-20	30.137 mi
Registration #5	2012-12-24	35.272 mi
Registration #6	2014-01-15	41.957 mi
Registration #7	2015-01-15	48.067 mi
Registration #8	2015-01-22	48.117 mi
Registration #9	2015-12-03	54.205 mi
Registration #10	2016-12-28	61.236 mi
Registration #11	2016-12-28	61.236 mi
Registration #12	2016-12-28	61.236 mi
Registration #13	2016-12-28	61.236 mi
Registration #14	2016-12-28	61.236 mi
Registration #15	2016-12-28	61.236 mi
Registration #16	2016-12-28	61.236 mi
Registration #17	2016-12-28	61.236 mi
Registration #18	2016-12-28	61.236 mi
Registration #19	2016-12-28	61.236 mi
Registration #20	2016-12-28	61.236 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 255340