





General information

Make	FIAT
Model	TIPO MULTIJET LOUNGE
Colour	Black
Year of manufacture	2017
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	99 g/km
CO2 label	А





Internet history

Entry 2

Date Pictures

Listing price

2023-08-30 12

12

View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price


8

2022-02-01

View report



source: cargurus.co.uk











MOT history

MOT expiry date	2024-09-25
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	20
Total items failed	3

MOT #10	2023-09-26 09:54
MOT test number	651826701602
Result	✓ Passed
Next expiry date	2024-09-25

МОТ #9	2023-01-04 13:31
MOT test number	424113364309
Result	✓ Passed

MOT #8		2023-01-04 11:04
MOT test	number	348490370439
Result		🗙 Failed
MAJOR MAJOR	Headlamp not working on dipped beam Both (4.1.1 (a) (ii)) Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	

MOT #7	2022-02-18 09:11
MOT test number	589311554043
Result	✓ Passed





MOT #6	2022-02-04 10:09
MOT test	number 634293400496
Result	× Failed
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #5		2021-12-09 13:06
MOT test	number	383573489345
Result		✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #4		2021-12-09 13:06
MOT test number		773933654472
Result		🗙 Failed
Advice Nearside Rear S	nock absorbers has light misting of oil (5.3.2 (b))	
Pass with rectification	Nearside Front Windscreen wiper does not clear the	ne windscreen effectively (3.4
(b) (ii))		
Advice Offside Rear Sho	ck absorbers has light misting of oil (5.3.2 (b))	



W	01	.7	0	D	Μ
	repor	t da	te: 2	024-	03-28

MOT #3		2020-12-15 11:04
MOT test	number	805110158555
Result		✓ Passed
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect	(5.3.2 (b))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effe	ect (5.3.2 (b))

MOT #2	2020-12-15 11:04
MOT test number	598845709432
Result	× Failed
Advice Nearside Rear S	hock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice Nearside Front S	ervice brake fluctuating, but not excessively (1.2.1 (e))
Pass with rectification	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice Offside Rear Sho	ock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Pass with rectification	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice Front Brake pad	(s) wearing thin (1.1.13 (a) (ii))

MOT #1	2020-06-04 05:55
MOT test number	364311014326
Result	✓ Passed
Advice COVID-19 6 MONTH EXTENSION	



Tax & MOT check

√ Taxed	✓ MOT
Tax due: 1 October 2024	Expires: 25 September 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Duniuge 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-06-12
Last registration	2023-09-26
Complete history	See info



Registration #1	2017-06-12	10 mi
Registration #2	2020-12-15	46.188 mi
Registration #3	2020-12-15	46.188 mi
Registration #4	2021-12-09	64.199 mi
Registration #5	2021-12-09	64.199 mi
Registration #6		11.777 esi
Registration #7		11.117 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.277 esi



WO170DM report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
S0482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Dimensions & weight	
Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1365 kg
Max. allowed weight	1790 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	6330844