



report date: 2024-03-29

General information

Make	KIA
Model	VENGA 1 AIR ECODYNAMICS
Colour	Silver
Year of manufacture	2015
Top speed	103 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 4.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 2

Date	2021-08-26
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-26
Pictures	26
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-13
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	11
Total items failed	3

MOT #9	2023-08-14 15:20
MOT test number	809725394797
Result	✓ Passed
Next expiry date	2024-08-13
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2022-06-24 09:29
MOT test number	804123119520
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2022-06-24 09:29**MOT test number** 788934377864**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2021-06-19 09:13**MOT test number** 157304177265**Result** ✓ Passed**MOT #5** 2020-05-29 11:19**MOT test number** 289913506001**Result** ✓ Passed**MOT #4** 2020-05-29 11:19**MOT test number** 488939989616**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #3** 2019-06-22 10:08**MOT test number** 187364511347**Result** ✓ Passed**MOT #2** 2019-06-22 10:08**MOT test number** 424499733573**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



MOT #1	2018-06-13 14:28
MOT test number	597748322140
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
13 August 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	13 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	EF15XOP
Plate since	2019-03-29
Current registration	EF15XOP
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-06-26
Last registration	2023-08-14
Complete history	See info



Registration #1	2015-06-26	11 mi
Registration #2	2018-06-13	17.253 mi
Registration #3	2019-06-22	28.567 mi
Registration #4	2019-06-22	28.567 mi
Registration #5	2020-05-29	38.372 mi
Registration #6	2020-05-29	38.372 mi
Registration #7	2020-05-29	38.372 mi
Registration #8	2020-05-29	38.372 mi
Registration #9	2020-05-29	38.372 mi
Registration #10	2020-05-29	38.372 mi
Registration #11	2020-05-29	38.372 mi
Registration #12	2020-05-29	38.372 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4068 mm
Wheel base	2615 mm
Kerb weight	1343 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FAEZ091955